

MILLINGTON, TN LITTLE ROCK, AR

Job Information

Job #:	94795				Date:	October 9, 2018
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Sage V Foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Marathon	Enclosure :	Totally Enclosed Fan Cooled
Serial#:		Model#:	PVF25TTWD6031 AAM
Service Factor:	1.15	Frame:	
Horsepower/kW:	10	Rated RPM:	1765
Rated Amps:	26.8/13.4	Rated Voltage:	230/460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2

Тор













WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	_	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	NSK
Insulated:	No	Bearing DE Size:	6209 2RS
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6207 2RS
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Bearing Retainer Image

Thermal Protection





MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Grease	Thermal Protection device DE:	_
Unknown	Thermal Protection device ODE:	_
Unknown		
1/4	Grease Cond. DE:	New
1/4	Grease Cond. ODE:	New
Other TA 1491 2191 0250 Worn	Seals Image:	
Other 23458 Worn	Seals Image 2:	
	Unknown Unknown 1/4 1/4 Other TA 1491 2191 0250 Worn Other 23458	UnknownThermal Protection device ODE:Unknown1/4Grease Cond. DE:1/4Grease Cond. ODE:OtherSeals Image:TA 1491 2191 0250WornSeals Image 2:OtherSeals Image 2:OtherSeals Image 2:

Shaft damage cause:

Other

Shaft Image:



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: Broken Frame cond.: Good



Endbell Image:



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

J-Box cover

HH cover

O-rings J-Box Glands

None





Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	9	Terminal Markings:		
Length of leads:	10"	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Red	ceived: 460 volts	
Lug Condition:	_	٢	Ferminal	Lugs
Lug size:				
Lug Attachment:	-			



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)

Rotor Type: Rotor Condition:	Cast Aluminum	Num rotor bars: Num broken bars:		Rotor
Rotor Test Results Visual: Pass	Growle	er: Pass	Single phase:	Pass
Stator type:	Factory	If other, stator ty	'pe:	
Stator condition:	Ok	If other, stator condition	ion:	
Failure location:	Other	If other, stator faile	ure:	
Stator Image:				

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)

Winding color:	Painted	Winding	g image	Winding Thermal	Protection:	No	
Winding condition :	Solid						
Winding Thermal Protection DE:	_						
Winding Thermal Protection ODE:							
Stator test results:	Salvageable						
Megs incoming: G	iood	Surge incoming:	Good	Hi-pot inc	coming:	Good	
Winding Resistance I	ncoming						
Pha	ses A to B	Phases B to C	Phase	s C to A	Resistive in	mbalance	
Incoming 0.7	52	0.753	0.752		0.0		
Leads/jumpers: Ok							
If other, leads/jumpers:							
Mechanical Ins	pection						
Inspect bolt holes and	asteners. Validat	te correct fasteners.					

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Damaged	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6209 2RS
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6207 2RS

Retainer condition:

n: Good

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good	
Seals DE type:	Other	If DE undersized, amt.:		
Seals DE size:	1491 2191 0250	Brg. Seats ODE:	Good	
Seals DE (inbound) condition :	Bad	If ODE undersized, amt.:		
Seals ODE condition :	Worn	Shaft damage:	Salvageable	
Seals ODE type:	Other			
Seals ODE size:	23458	Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :	Bad	Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	3.3465	Foot flatness:	Pass	
Endbell DE insulated?:	No	Does Air Gap Meet Cus	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	2.8354	variation)?		
Endbell ODE insulated?:	No	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Motor- Fan has broken blades, DE seal surface bad

Cause of Failure

Comments

Motor-DE seal surface needs to be repaired, cooling fan needs to be replaced Gearbox- Input gears bad(2), needs 3 seal surfaces repaired, new bearings and seals, replace intermediate shaft

Service Tech name: Ly

Lynn McDonald

Service Tech signature:

Lynn McAmald

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301