

## **Job Information**

94821 Job #: Date: October 22,

2018

Priority: Authorized OT: No Authorized by:

# **Customer Information**

Name: Sage Reason:

Contact: Motor#: PO#:

Application: Special notes:

## **Name Plate Information**

Manufacturer: **BALDOR** Enclosure: Totally Enclosed **Enclosure Type image** 

Non-Ventilated

10G517X209G2 Serial#: Model#:

Service Factor: 284T Frame:

Horsepower/kW: 25 Rated RPM: 1770

Rated Amps: 60/30 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top















## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Yes None

> Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

No present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: **RBC** 

Insulated: Bearing DE Size: 6311 2RS No

Bearings ODE: Worn Bearings ODE make: **FAG** 

Bearing Type: Bearing ODE Size: 6309 2RS Ball

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





## **Mechanical Inspection (Continued)**

Lubrication Type: Grease Thermal Protection device DE: N/A

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: N/A

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Seals Image: Other

Seals DE size:

Seals DE (inbound) condition: Good

Seals Image 2:

Seals ODE type:

N/A

Seals ODE size:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:

Not Available

Fax 901-873-5301



# **Mechanical Inspection (Continued)**





Bushings/sleeves image:



Water jacket: N

N/A

Fan:

N/A

Endbell Image:

Frame cond.:

Good

Not Available Not Available



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None



Other missing parts

Lugs



## **Mechanical Inspection (Continued)**

### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

## **AC Electrical Inspection**

Number of leads: 9 Terminal Markings: 1-9

Length of leads: 18" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

Terminal

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: High voltage Lug type:

Not Not Lug Attachment: — Available Available

Lug Condition:

Lug size:



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



### **Rotor Test Results**

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:





Not

Available



## **AC Electrical Inspection (Continued)**

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Surge incoming: Hi-pot incoming: Good Good Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.306 0.303 0.306 1.1

> Leads/jumpers: Lead jumper Image. : Ok

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

**Shaft Condition:** Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6311 2RS

Shaft runout(TIR-Inbound): Bearing ODE Size: 6309 2RS

Retainer condition:

ax 901-873-5301



## **Mechanical Inspection (Continued)**

Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: Good If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.7252 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

3.9379



## Conclusion

**Component Failure** 

**Cause of Failure** 

#### **Comments**

DE AND ODE BEARINGS HAD SIGNS OF FROSTING THEY ALSO HAD SKID MARKS ON RACES

Service Tech name: Robert Wiley

Service Tech signature: