

Job Information

Job #: 94835 Date: October 30,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Future Fuel Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Siemens Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled Serial#: 51-380-402 Model#: 639

Service Factor: 1.0 Frame: 364T

Horsepower/kW: 40 Rated RPM: 1170

Rated Amps: 94.6/47.3 Rated Voltage: 230/460

Phase: 3 Cycles: 60

·

No

Nameplate DE ODE F1 F2 Top



Special design:













Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Water

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): 0.001

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6313z

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6313z

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: Watery

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.: Good





Endbell type: Motor Mount Position: Horizontal/Foot mount Single piece

Missing parts? Endbell Image:

☐ J-Box ☐ J-Box cover O-rings

✓ None ☐ HH cover Glands





Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 4

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads: 8awg

P2-Brown 2-White 6-No color assigned

3-Orange 7-No color assigned 4-Yellow 8-Red Lead condition: Worn

Connections As Received: P1

Eyelet Lug type:

Lug Condition: Good Terminal Lugs

Lug size: 8awg

Lug Attachment:

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 55

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Other If other, stator condition:

Failure location: Connection If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6313z

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6313z

Retainer condition: Good

hone 901-873-5300

ax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 5.5122 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

5.5124



Conclusion

Component Fa	i	lure	•
--------------	---	------	---

Windings

Cause of Failure

Water in stator caused connection to short out and blow.

Comments

Service Tech name: Trevor Hall

Service Tech signature:

Thell