

Job Information

94838 Job #: Date: October 25,

2018

Priority: Authorized OT: No Authorized by:

Customer Information

Name: **AFT** Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Serial#:

Manufacturer: **BARTEC VARNOST** Enclosure: Totally Enclosed **Enclosure Type image**

> Fan Cooled 3KTC-180N-2

Model#:

Service Factor: 180M Frame:

Horsepower/kW: **26KW** Rated RPM: 3525

Rated Amps: 71/41 Rated Voltage: 278/480

Phase: Cycles: 3 60

Special design:

No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device Yes Contaminant Image:

present?:

Type of grounding device: Ageis Not Available

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6310 ZZ

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6310 ZZ

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Seals Image: Other

Seals DE size: 50 78 10

Seals DE (inbound) condition: Good

Seals ODE type:

Seals Image 2:

Seals ODE size: 50 78 10

Seals ODE (inbound) condition Good

Other

Shaft damage cause: Shaft Image: None



Fax 901-873-5301

CENTRAL ARKANSAS



Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good

Not Available



Endbell type: S

Single piece

Motor Mount Position:

Missing parts?

Horizontal/Foot mount

Endbell Image:





☐ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings: UVW

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads:

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: Acceptable



Not Available



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok ____

Num broken bars:

Num rotor bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass


Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:





Not

Available



AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Good Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Surge incoming: Hi-pot incoming: Good Good Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.262 0.262 0.261 0.2

> Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6310

Shaft runout(TIR-Inbound): Bearing ODE Size: 6310

Retainer condition:

Fax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: Good If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: Other

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3313 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

4.3313

sect Milan



Conclusion

Component Failure

Cause of Failure

Comments

Ageis Ring Needs To BE REPLACED

Service Tech name: Robert Wiley

Service Tech signature: