

Job Information

Job #: 94852 Date: November 7,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: North American Electric Motors Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: North American Enclosure: Weather Protected Enclosure Type image

Electric I (WPI)

Serial#: 1601140-SB-YS Model#: NAE-VHS-60-4-

PWS

Service Factor: 1.15 Frame: 364TP-WP1

Horsepower/kW: 60 Rated RPM: 1770

Rated Amps: 73 Rated Voltage: 460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:











Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 7224 BM


Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Spherical-roller thrust Bearing ODE Size: 6314

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Oil Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: Full Grease Cond. ODE: Other

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 17"

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition:

Connections As Received: Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ground If other, stator condition:

Failure location: Core edge If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Painted Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.678 0.660 0.669 2.8

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 7224 BM

Shaft runout(TIR-Inbound): Bearing ODE Size: 6314

Retainer condition: Good

Fax 901-873-5301



Seals DE condition : None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

5.9063



Conclusion

Com	pone	nt F	ailure
-----	------	------	--------

Windings grounded/shorted

Cause of Failure

Windings shorted on the connection end at the core edge

Comments

Lower bearing has some pitting on races most likely from foreign debris in bearing

Lynn M. Dohuld

Service Tech name: Lynn McDonald

Service Tech signature: