

Job Information

Job #: 95051 Date: December 31,

2018

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Capital Hotel Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: ELMO Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 0644.12796900 Model#: CF132H+/G-4-

T-4204

Service Factor: Frame:

Horsepower/kW: Rated RPM:

Rated Amps: Rated Voltage:

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top









Not Available

Not Available

CENTRAL ARKANSAS



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6307 ZZ

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6307 ZZ

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: N/A Grease Cond. DE: New

Grease Amt ODE: N/A Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket: N/A Fan: N/A Frame cond.: Good



Endbell type: Motor Mount Position: Horizontal/Foot mount Single piece

Missing parts? Endbell Image:

☐ J-Box cover O-rings ☐ J-Box

☐ HH cover Glands

✓ None



Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: — Terminal Markings:

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: — Not Available Available

Fax 901-873-5301

Failure Image:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Stator Image:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Not Available

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Not

Available

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: — Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6307

Shaft runout(TIR-Inbound): Bearing ODE Size: 6307

Retainer condition: —

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition : If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.1504 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

3.1502



Conclusion

Component Failure

Cause of Failure

Comments

Stator shorted at the slot

Service Tech name: Robert Wiley

Service Tech signature:

Fax 901-873-5301