

Job Information

Job #:	95066				Date:	January 23, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Delta Plastics		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	A1207242103	Model#:	A36-1126-1822
Service Factor:	1.15	Frame:	364T
Horsepower/kW:	60	Rated RPM:	1780
Rated Amps:	135/68.7	Rated Voltage:	230/460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Тор

Nameplate

DE

ODE

F1

F2









WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	Νο	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6313 2Z
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6313 2Z
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Bearing Make Image

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Gritty
Grease Amt ODE:	Full	Grease Cond. ODE:	Gritty
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	




VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	9	Terminal Markings:			
Length of leads:	9"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	Good	4-Yellow	8-Red		
Lug type:		Connections As Re	eceived:		
Lug Condition:	_		Terminal	Lugs	
Lug size:					
Lug Attachment:	_				

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color	r: Still has color	Winding	g image Windi	ng Thermal Protection	on: Yes
Winding condition	: Solid				AC many 1 years 410 V GS - 0 15 13 23 Team C B B A C
Winding Therma Protection DE					B 25 25 2000 m B 2000 m S 2000 m GO W K 25 00 m S 2000 m S 2000 m B 2000 m B 2000 m S 2000 m S 2000 m B 2000 m B 2000 m S 2000 m S 2000 m B 2000 m B 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m S 2000 m B 2000 m S 2000 m S 2000 m
Winding Therma Protection ODE					
Stator test results	: Salvageable				
Megs incoming:	Good	Surge incoming:	Good	Hi-pot incoming:	Good
Winding Resistanc	e Incoming				
Р	hases A to B	Phases B to C	Phases C to	A Resistiv	e imbalance
Incoming ().107	0.106	0.107	0.8	
Leads/ju If other, leads/ju			Lead jump	er Image. :	
Mechanical I	-				
Inspect bolt holes ar	nd fasteners. Valida	te correct fasteners.			
Shaft C	Condition: Good		Bearings Reta	iner: Yes	

Type of grounding device:NoneBearing DE Size:6313 2Z/C3Shaft runout(TIR-Inbound):Bearing ODE Size:6313 2Z/C3

Retainer condition:

on: Good

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.5127	Foot flatness:	Pass
Endbell DE insulated?:	No		stomer or EASA spec(<10%
Endbell ODE size:	5.5128	variation)?	
Endbell ODE insulated?:	No		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Numerous cracks and welds need repairs on blower housing. Motor fan & connection box broken. Motor o.d.e end bell housing needs 4 fan cover mount bolt holes drilled and tapped

Cause of Failure

Multiple failed welds on blower housing. Unit was apparently dropped by customer in the loading process during delivery.

Comments

Extensive welding and repair required on blower housing.

Service Tech name: **Terrence Holland**

Service Tech signature:

Perrence Hollan

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053

Phone 901-873-5300

Fax 901-873-5301

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

CENTRAL ARKANSAS