

#### **Job Information**

Job #: 95232 Date: February 19,

2019

Priority: — Authorized OT: No Authorized by:

**Customer Information** 

Name: Almatis Reason:

Contact: Motor#: PO#:

Application: – Special notes:

**Name Plate Information** 

Manufacturer: Derrick Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: F-996 Model#: F5-36-4601480-6

Service Factor: 1.10 Frame:

Horsepower/kW: 1.5 Rated RPM: 3600

Rated Amps: 2.5 Rated Voltage: 460/480

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6315 2Z/C3

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6315 2Z/C3

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 —

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

### **AC Electrical Inspection**

Number of leads: 3 Terminal Markings:

Length of leads: 4'8" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:





Fax 901-873-5301



## **AC Electrical Inspection (Continued)**


Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind



Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 499.9 499.9

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:



# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6315-2Z/C3

Shaft runout(TIR-Inbound): Bearing ODE Size: 6315-2Z/C3

Retainer condition: —



Seals DE condition : None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)? Endbell ODE size:

Endbell ODE insulated?: No

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### Conclusion

**Component Failure** 

Windings.

**Cause of Failure** 

Comments

Rewind required. Fits check good.

Service Tech name: Terrence Holland

Service Tech signature: