

Job Information

Job #:	95233				Date:	March 11, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Almatis		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	US ELECTRIC	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:	Z07Z134R100M	Model#:	7975B	
Service Factor:	1.15	Frame:	365T	
Horsepower/kW:	75	Rated RPM:	1780	
Rated Amps:	86	Rated Voltage:	460	
Phase:	3	Cycles:	60	
Special design:	No			



DE

ODE

F2

Тор









F1

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6313 2Z-C3
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6212 2Z-C3
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Water jacket:	Ok	Fan:	Ok	Frame co	nd.: Good
Motor Mount Po	sition: Horizontal/F			Endbell type:	Single piece
				Lindben type.	
Missing parts					
J-Box cove	r 🗌 O-rings	J-Box			
HH cover	Glands	None None			
Other missing p	parts				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap M	eaurements (N/A on Single Piece E	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	3	Terminal Markings:	
Length of leads:	7inch	REF: NEMA Stds. MG 1-2009, Rev. 1- Markings Identified By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue5-Black2-White6-No color assigned3-Orange7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow 8-Red	
Lug type:		Connections As Received:	
Lug Condition:	Good	Terminal	Lugs
Lug size:			
Lug Attachment:	_		

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image Wind	ling Thermal Protectic	on: No	
Winding condition :	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:	_	TE				
Stator test results:	Salvageable					
Megs incoming:	Good	Surge incoming:	Good	Hi-pot incoming:	Good	
Winding Resistance	Incoming					
Ph	ases A to B	Phases B to C	Phases C to	A Resistive	e imbalance	
Incoming 3.	5	3.0	3.0			
Leads/jun	npers: Ok		Lead jump	per Image. :	nalyzer 2 CREETCH	
If other, leads/jun	npers:				Mint Dis Mint <thm< td=""></thm<>	
Mechanical Inspection						
Inspect bolt holes and	l fasteners. Valida	te correct fasteners.				
Shaft Co	ondition: Good		Bearings Reta	ainer: Yes		

Bearing DE Size:

Bearing ODE Size:

6313 2Z-C3

6212 2Z-C3

Type of grounding device:

Shaft runout(TIR-Inbound):

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.5145 BAD	Foot flatness:	Pass
Endbell DE insulated?:	_	Does Air Gap Meet Cus	tomer or EASA spec(<10%
Endbell ODE size:	4.3312	variation)?	
Endbell ODE insulated?:	_	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Worn bearings

Cause of Failure

D.E. End bell was out of tolerance

Comments

The Drive End Bell Housing was worn the the point it was oversized

Service Tech name:

Chris Wiley

Service Tech signature:

Con Unlov

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301