

Job Information

Job #: 95292 Date: February 28,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Delta Plastics Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Baldor Enclosure: Open Drop Proof Enclosure Type image

Model#:

(ODP)

Serial#: M9129530-010001L

Q

Service Factor: 1.0 Frame: URL7882

Horsepower/kW: 150 Rated RPM: 1755/2000

Rated Amps: 180 Rated Voltage: 460

Phase: 3 Cycles: 60/68

Special design: No

Nameplate DE ODE F1 F2 Top









Contaminant Image:



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: NACHI

Insulated: No Bearing DE Size: NU-215-C3

Bearings ODE: Worn Bearings ODE make: NACHI

Bearing Type: Ball Bearing ODE Size: 6211-C3

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: Thermocouple

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: Thermal Overloads

Lubrication brand inbound: Unknown Thermal Protection device ODE: Thermal Overloads

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Charred

Grease Amt ODE: Full Grease Cond. ODE: Charred

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

✓ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 10inch REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type: Na

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 39

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Good

Winding Thermal

Stator test results: Salvageable

Protection DE: Good Protection ODE:

Megs incoming: Surge incoming: Hi-pot incoming: Good Good Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 2.9 3.3 2.8

> Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: NU-215-C3

Shaft runout(TIR-Inbound): Bearing ODE Size: 0.001 6211-C3

Retainer condition: Good

ax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 5.1183 Foot flatness: Pass

Endbell DE insulated?: —

3.9370

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:

Ova Hun



Conclusion

Component Fa	ailure
--------------	--------

Bearings

Cause of Failure

Bearings were worn

Comments

Bearings were worn from contaminated grease. Recommend Aegis ring

Service Tech name: Chris Wiley

Service Tech signature: