

Job Information

Job #: 95515 Date: April 29, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Advanced Fluid Technologies Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: BARTEC VARNOST Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 200941670 Model#: 3KTC180M-2

Service Factor: Frame:

Horsepower/kW: 26 Rated RPM: 3525

Rated Amps: Rated Voltage: 480

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?: '

No

Type of grounding device:

Shaft runout(TIR-Inbound): 0.002

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6310-2Z-L038-C3

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6310-2Z-L038-C3

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Isolators Seals Image:

Seals DE size: 50x72x10

Seals ODE type: Isolators

Seals ODE size: 50x72x10

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301

CENTRAL ARKANSAS



Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.:





Good

Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box ☐ J-Box cover O-rings

✓ None ☐ HH cover Glands



Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 4in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: — 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars:

Rotor

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6310-2Z-L038-C3

Shaft runout(TIR-Inbound): 0.002 Bearing ODE Size: 6310-2Z-L038-C3

Retainer condition: —

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

x 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Isolators If DE undersized, amt.:

Seals DE size: 50x72x10 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Isolators

Seals ODE size: 50x72x10 Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3314 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size: 4.3313

Endbell ODE insulated?: —

Char Elwy



Conclusion

Component Failure

Cause of Failure

Comments

Bearings showed signs of wear

Service Tech name: Chris Wiley

Service Tech signature:

Fax 901-873-5301