

## **Job Information**

Job #:	95539				Date:	May 17, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

## **Customer Information**

Name:	Community Water System		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

Manufacturer:	U.S. Motors	Enclosure :	Weather Protected I (WPI)	Enclo
Serial#:	H0603044798-100R- 01	Model#:	7228-BCBQ-2	
Service Factor:	1.15	Frame:	5008VPH	à
Horsepower/kW:	400	Rated RPM:	1780	
Rated Amps:	436	Rated Voltage:	400	
Phase:	3	Cycles:	60	
Special design:	No			

#### Enclosure Type image



Nameplate

DE

ODE

F1

F2

Тор







VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	Коуо
Insulated:	No	Bearing DE Size:	7228 B 5G C3
Bearings ODE:	Worn	Bearings ODE make:	Коуо
Bearing Type:	Ball	Bearing ODE Size:	6219 Z C3
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	Good	Thermal Protection Type:	Thermocouple

#### Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



**Thermal Protection** 



# **Mechanical Inspection (Continued)**

Lubrication Type:	Oil	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	Isolators		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **Mechanical Inspection (Continued)**

Brg. Image:



Water	jacket:	N/A
-------	---------	-----

N/A

Fan:

N/A

Endbell Image:

Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

O-rings

Glands

Endbell type:

Single piece

B



Other missing parts

Missing parts?

J-Box cover

HH cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

J-Box

None



# **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

# **AC Electrical Inspection**

Number of leads:	6	Terminal Markings:	:			
Length of leads:	18	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As R	eceived:			
Lug Condition:	Good		Terminal	Lugs		
Lug size:				51		
Lug Attachment:	Acceptable					

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type:	Cast Aluminum			Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars: 0		
Rotor Test Results				
Visual: Pass	Grow	ler: Pass	Single phase:	Pass
Stator type: Stator condition:	Factory Ok	If other, stator ty If other, stator conditi		
Failure location:	Other	If other, stator failu	ire:	
Stator Image:				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **AC Electrical Inspection (Continued)**

Winding color:	Like new	Winding	j image	Winding Thermal	I Protection	: Yes	
Winding condition :	Solid						
Winding Thermal Protection DE:	_						
Winding Thermal Protection ODE:	_						
Stator test results:	Rewind						
Megs incoming: G	ood	Surge incoming:	Good	Hi-pot ind	coming:	Good	
Winding Resistance I	ncoming						
Phas	ses A to B	Phases B to C	Phase	es C to A	Resistive i	mbalance	
Incoming							
Leads/jump	oers: Ok						
If other, leads/jump	oers:						

# **Mechanical Inspection**

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	7228B 5G C3
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6219 Z
Retainer condition:	Good		



# **Mechanical Inspection (Continued)**

Seals DE condition :	None	Brg. Seats DE:	Good	
Seals DE type:	N/A	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	Other	Shaft damage:	ОК	
Seals ODE type:	Isolators			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	Too tight	Foot flatness:	Pass	
Endbell DE insulated?:	No	Does Air Gap Meet Cu	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	6.629	variation)?		
Endbell ODE insulated?:	No	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

#### **Component Failure**

**Cause of Failure** 

Customer requests reconditioning of motor assembly.

#### Comments

D.E. End bell top housing fit was extremely tight on both bearings and needs to be loosened up.

Service Tech name: Terrence Holland

Service Tech signature:

Alla

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301