

Job Information

Job #:	95547				Date:	May 8, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	e: Sage V Foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	BALDOR	Enclosure :	Totally Enclosed Non-Ventilated
Serial#:	C1710160492	Model#:	Spec: 10G517X209G2
Service Factor:	1.15	Frame:	284T
Horsepower/kW:	25	Rated RPM:	1770
Rated Amps:	60/30	Rated Voltage:	230/460
Phase:	3	Cycles:	60

Enclosure Type image



Тор

Nameplate

Special design:

DE

No

ODE

F1

F2









WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	6311 2RS
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6309 2RS
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254 Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	Other
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



N/A

Fan:

N/A

Frame cond.: Good



 Motor Mount Position:
 Horizontal/Foot mount
 Endbell type:
 Single piece

 Missing parts?
 Endbell Image:
 Endbell Image:
 Image:



Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	9	Terminal Markings:				
Length of leads:	14 in	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	_	4-Yellow	8-Red			
Lug type:		Connections As R	eceived:			
Lug Condition:	_		Terminal	Lugs		
Lug size:						
Lug Attachment:	_					

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image	Winding Therma	al Protection	: No		
Winding condition :	Solid							
Winding Thermal Protection DE:	_							
Winding Thermal Protection ODE:	_							
Stator test results:	Salvageable							
Megs incoming: C	Good	Surge incoming:	Good	Hi-pot in	ncoming:	Good		
Winding Resistance	ncoming							
Pha	ses A to B	Phases B to C	Phases	s C to A	Resistive i	imbalance		
Incoming 0.0	0	0.00	0.00					
Leads/jum	pers: Ok							
If other, leads/jumpers:								
Mechanical Inspection								
Inspect bolt holes and	fasteners. Valida	te correct fasteners.						

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6311 2Rs
Shaft runout(TIR-Inbound):	0.001	Bearing ODE Size:	6309 2RS

Retainer condition: Good

 WEST TENNESSEE
 CENTRAL ARKANSAS

 7030 Ryburn Drive
 6812 Lindsey Rd.

 Millington, TN 38053
 Little Rock, AR 72206

 Phone 901-873-5300
 Phone 501-375-9178

 Fax 901-873-5301
 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good	
Seals DE type:	N/A	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	None	Shaft damage:	ОК	
Seals ODE type:	N/A			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	4.7246	Foot flatness:	Pass	
Endbell DE insulated?:	-		stomer or EASA spec(<10%	
Endbell ODE size:	3.9382-3.9383-3.9383. Bad	variation)?		
Endbell ODE insulated?:	_			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Bearings showed signs of wear and the inner race showed signs of frosting. The ODE housing was oversized. Recommend reconditioning

Service Tech name:

Chris Wiley

Service Tech signature:

mus Willy

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301