

Job Information

Job #: 95626 Date: June 10, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Future Fuel Chemical Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Sirens Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: Model#: N3 100

Service Factor: 1.15 Frame: 444t

Horsepower/kW: 150 Rated RPM: 1780

Rated Amps: 169 Rated Voltage: 460

Phase: 3 Cycles:

No

Nameplate DE ODE F1 F2 Top



Special design:







Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Dirt

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

 $Shaft\ runout (TIR-Inbound):$

Type of grounding device:

Bearings DE: Worn Bearings DE make: NTN

Insulated: No Bearing DE Size: 6318

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Ball Bearing ODE Size: 6214

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 **ODE @ 180**

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 13 inches

Markings Identified By Color:

P1-No color assigned 1-Blue 5-Black Size of leads:

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment:





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 58

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Painted Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6318

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6214

Retainer condition: —

Fax 901-873-5301



Seals DE condition : None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 7.4836 has lip Foot flatness: Pass

Endbell DE insulated?: -

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:

4.9218



Conclusion

Component Failure

Cause of Failure

Comments

Drive end bearing failed from metal fatigue. Grease was old and hardened. Drive end housing has a lip in the bearing seat

Chris Ellely

Service Tech name: Chris Wiley

Service Tech signature: