

Job Information

Job #:	95628				Date:	June 17, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Welspun		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Bell&Gossett	Enclosure :	Open Drop Proof (ODP)	Enclosure Type image
Serial#:		Model#:		p # 18
Service Factor:		Frame:		e 1
Horsepower/kW:		Rated RPM:		
Rated Amps:		Rated Voltage:		
Phase:		Cycles:		
Special design:	No			

Nameplate

ODE

F1

F2

Тор

Not Available











WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	None
Shaft rotation:	CW	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6308
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6308
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 Bearing Make Image



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type: Seals DE size:	Slinger	Seals Image:	
Seals DE (inbound) condition : Seals ODE type: Seals ODE size: Seals ODE (inbound) condition	Slinger	Seals Image 2:	
Shaft damage cause:	None	Shaft Image:	



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:

Not Available





Mechanical Inspection (Continued)

Air Gap Mo	eaurements (N/A on Single Piece E	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	_	Terminal Markings:		
Length of leads:		REF: NEMA Std Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	_	4-Yellow	8-Red	
Lug type:		Connections As Re	ceived:	
Lug Condition:	_	-	Terminal	Lugs
Lug size:			N1 /	
Lug Attachment:	_		Not ailable	Not Available

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color	: Like new	Winding	g image M	/inding Thermal Protec	tion: No
Winding condition	: Solid				
Winding Therma Protection DE		Not Available			
Winding Therma Protection ODE					
Stator test results	: Rewind				
Megs incoming:	Good	Surge incoming:	Good	Hi-pot incoming	Good
Winding Resistance	e Incoming				
Pł	nases A to B	Phases B to C	Phases (C to A Resist	ive imbalance
Incoming 0	.00	0.00	0.00	0.00	
Leads/ju	mpers: Ok		Lead ju	umper Image. :	
If other, leads/ju	mpers:				Not Available

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6308
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6308

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	1.5751
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	1.5750
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.5442	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Cu	stomer or EASA spec(<10%
Endbell ODE size:	3.5434	variation)?	
Endbell ODE insulated?:	No	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Bearings seals and clean

Service Tech name: Ro

Robert Wiley

Service Tech signature:

Sect Unler

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301