

Job Information

Job #:	95669				Date:	July 26, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Saint Jean Industries		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Lesson	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	180069	Model#:	C132TZF248A
Service Factor:		Frame:	DF132MD
Horsepower/kW:	10	Rated RPM:	1765
Rated Amps:	24/12	Rated Voltage:	230/460
Phase:	3	Cycles:	
Special design:	No		

Enclosure Type image



Тор

Nameplate

DE

ODE

F1

F2







WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Water
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	NSK
Insulated:	No	Bearing DE Size:	6308
Bearings ODE:	Worn	Bearings ODE make:	NSK
Bearing Type:	Ball	Bearing ODE Size:	6207
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



nage Bearing Retainer Image



Thermal Protection

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	1/4	Grease Cond. DE:	Watery
Grease Amt ODE:	1/4	Grease Cond. ODE:	Watery
Seals DE type:	Other	Seals Image:	
Seals DE size:	40-56-8		
Seals DE (inbound) condition :			A CONTRACTOR
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket:	N/A		Fan:	Broken	Frame cor	nd.:	Good
						the second s	
Motor Mount Pos	sition: Horizontal/F	oot mount			Endbell type:	Single	e piece
Missing parts	?			Endbell Image:			
J-Box cover	O-rings	J-Box					District in
HH cover	Glands	Vone			A R		
Other missing p	arts						

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	9	Terminal Markings:			
Length of leads:	4 inch	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	Good	4-Yellow	8-Red		
Lug type:		Connections As Re	ceived:		
Lug Condition:	_		Terminal	Lugs	
Lug size:					
Lug Attachment:	_				





AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Still has color	Winding	g image	Winding Therma	I Protection	: No
Winding condition :	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:	_					
Stator test results:	Salvageable					
Megs incoming: G	aood	Surge incoming:	Good	Hi-pot in	coming:	Good
Winding Resistance I	ncoming					
Pha	ses A to B	Phases B to C	Phases	C to A	Resistive i	mbalance
Incoming 0.00	0	0.00	0.00			
Leads/jump	oers: Ok		Lead	jumper Image. :		
If other, leads/jump	pers:					
Mechanical Ins	spection					
Inspect bolt holes and	fasteners. Validat	e correct fasteners.				

Shaft Condition:	Worn	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6308
Shaft runout(TIR-Inbound):	0.002	Bearing ODE Size:	6207

WEST TENNESSEECE7030 Ryburn Drive6812Millington, TN 38053LittlPhone 901-873-5300PhoFax 901-873-5301Fax

Retainer condition:

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Good



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Other	If DE undersized, amt.:	
Seals DE size:	40-56-8	Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	3.5441	Foot flatness:	Pass
Endbell DE insulated?:	_	Does Air Gap Meet Cus	stomer or EASA spec(<10%
Endbell ODE size:	2.8354	variation)?	
Endbell ODE insulated?:	_	—	

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Bearings failed due to water contamination & the shaft key way is stripped on the Drive End. Recommend reconditioning & shaft work.

Chris Wiley Service Tech name:

Service Tech signature:

Iron alily

WEST TENNESSEE

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301