

Job Information

Job #:	95671				Date:	July 3, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Mountain View		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

No

Manufacturer:	Aurora	Enclosure :	Open Drop Proof (ODP)
Serial#:	98114014-B	Model#:	
Service Factor:	1.15	Frame:	210
Horsepower/kW:	15	Rated RPM:	1747
Rated Amps:	19.9	Rated Voltage:	460
Phase:	3	Cycles:	60

Enclosure Type image



Nameplate

Special design:

DE

ODE

F1

F2

Тор







WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	None
Shaft rotation:	CCW	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):	.001		
Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	6311 2Z/C3
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	3305 A-2RS1/C3
Bearings Retainer:	Yes	Thermal Protection:	Yes

Retainer condition:

Bearing Type Image



Bearing Make Image

Bearing Retainer Image

Thermal Protection Type:

Thermal Protection

Thermocouple



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Good



Mechanical Inspection (Continued)

Lubrication Type:	Oil	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	0	Grease Cond. ODE:	Watery
Seals DE type: Seals DE size: Seals DE (inbound) condition :	Isolators	Seals Image:	
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition	Slinger	Seals Image 2:	S

Shaft damage cause:

None

Shaft Image:



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket:	N/A
---------------	-----

Fan:

N/A

Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece Missing parts? Endbell Image: O-rings J-Box cover J-Box HH cover Glands None



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	3	Terminal Markings:				
Length of leads:	10"	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As Re	eceived:			
Lug Condition:	_		Terminal	Lugs		
Lug size:						
Lug Attachment:	_					

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum				Rotor
Rotor Condition:	Ok	Num rotor bars: Num broken bars:	44 0		
Rotor Test Results Visual: Pass	Grow	vler: Pass		Single phase:	Pass
Stator type:	Factory	If othe	r, stator ty	pe:	
Stator condition:	Ok	lf other, sta	tor condition	on:	
Failure location:	In slot	If other,	stator failu	ire:	
Stator Image:					

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Still has color	Winding	ı image	Winding Thermal	I Protection:	Yes	
Winding condition :	Solid						
Winding Thermal Protection DE:	_	C C C C C C C C C C C C C C C C C C C					
Winding Thermal Protection ODE:	_						
Stator test results:	Rewind						
Megs incoming: Ba	ıd	Surge incoming:	Bad	Hi-pot ind	coming:	Bad	
Winding Resistance In	coming						
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive i	mbalance	
Incoming							
Leads/jumpe	ers: Ok						
If other, leads/jumpe	ers:						

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6311 2Z/C3
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	3305 A-2RS1/C3

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Slinger		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.7250	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Cus	tomer or EASA spec(<10%
Endbell ODE size:	2.4440 (undersized)	variation)?	
Endbell ODE insulated?:	No	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Seals, bearings.

Cause of Failure

Comments

Rewind stator and replace both cords. Replace all o rings and seals. Bottom bearing housing end bell measures too tight by .009.

Service Tech name: Terrence Holland

Service Tech signature:

Altro

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301