

Job Information

Job #: 95715 Date: July 12, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Plastic ingenuity Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Marathon Enclosure: Totally Enclosed Enclosure Type image

Non-Ventilated

Serial#: Model#: Svn182thy7726aa

11

Service Factor: Frame: 182TC

Horsepower/kW: 3 Rated RPM: 1755

Rated Amps: Rated Voltage: 230/460

Phase: Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Carbon No

> Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: Bearing DE Size: 6207 No

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Bearing ODE Size: Ball 6206

Bearings Retainer: Thermal Protection: No No

Retainer condition: Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: N/A Grease Cond. DE: New

Grease Amt ODE: N/A Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

☐ HH cover ☐ Glands ☑ None





Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 8 1/2 inch REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Failure Image:





AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6207

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6206

Retainer condition: -

ax 901-873-5301



Seals DE condition : None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 2.8380 Foot flatness: Pass

Endbell DE insulated?: —

2.4430

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:

Mar Gulley



Conclusion

Component Failure

Cause of Failure

Comments

Bearings showed signs of frosting and both end bells failed

Service Tech name: Chris Wiley

Service Tech signature:

Fax 901-873-5301