

Job Information

Job #: 95804 Date: July 29, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Searcy water Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Abs Enclosure: Open Drop Proof Enclosure Type image

8fm

(ODP)

0015868 Model#: Afpk20461me120/

Service Factor: Frame:

Horsepower/kW: 16 Rated RPM: 870

Rated Amps: 25.1 Rated Voltage: 460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:













present?:

Type of grounding device:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Water Yes

> Shaft rotation: **CCW** Contaminant(s) Amt: Cup

Shaft grounding device Yes Contaminant Image:

Shaft runout(TIR-Inbound):

Aegis

0.001

Bearings DE: Worn Bearings DE make: NSK

Insulated: Bearing DE Size: 3311b2rsrtngc3 No

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Bearing ODE Size: Ball 6308dvc3

Bearings Retainer: Thermal Protection: No No

Retainer condition: Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Oil Thermal Protection device DE:

Lubrication brand inbound: Unknown Thermal Protection device ODE:

Lubrication brand outbound: Unknown

> Grease Amt DE: Full Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Seals Image: Other

Seals DE size: Special

Seals DE (inbound) condition: Bad

Seals ODE type:

Seals Image 2:

Seals ODE size: Special

Seals ODE (inbound) condition Bad

Other

Shaft damage cause: Shaft Image: None



Fax 901-873-5301



Brg. Image:



Water jacket: Ok Fan: N/A Frame cond.: Good



Endbell type: Single piece

Missing parts? Endbell Image:

O-rings ☐ J-Box ☐ J-Box cover

Other

✓ None ☐ HH cover Glands





Other missing parts

Motor Mount Position:



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

Length of leads: 8" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 10 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned
Lead condition: Good 4-Yellow 8-Red

Connections As Received: 460

Lug type: Copper

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment:

10



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 60

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Other If other, stator type: Rewound

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Aegis Bearing DE Size: 3311b2rsrtngc3

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6308dvc3

Retainer condition: -

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: Special Brg. Seats ODE: Good

Seals DE (inbound) condition: Same If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Other

Seals ODE size: Special Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Same

Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.7249 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

3.5440



Conclusion

Component Fai	ilure
---------------	-------

Seals, bearings, o-rings

Cause of Failure

Trash in seals

Comments

Service Tech name: Trevor Hall

Service Tech signature:

7-Jrll