

Job Information

Job #: 95831 Date: August 1, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: AFT Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: HEW Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: Model#:

Service Factor: Frame: 160M

Horsepower/kW: 11KW Rated RPM: 3515

Rated Amps: 21.2 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE

CENTRAL ARKANSAS



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6309

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6309

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A Seals Image:

Seals DE (inbound) condition:

Seals DE size:

Seals Image

Seals ODE size:

Seals ODE type:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:


WEST TENNESSEE CENTRAL ARKANSAS 7030 Ryburn Drive 6812 Lindsey Rd.

6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

N/A

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Seals Image 2:





Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket: Ok

Not Available



Endbell Image:

Ok

Fan:

Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None



Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 6 Terminal Markings: 1-6

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 8"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 12

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: 460 Voltage

Lug type:

Lug Condition: Terminal Lugs

Lug size:

Lug Attachment:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Single phase: **Pass** Growler: Pass **Pass**

Stator type: If other, stator type: Factory

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image:



Failure Image:





AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

Not Available

Mechanical Inspection

If other, leads/jumpers:

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6309

Shaft runout(TIR-Inbound): Bearing ODE Size: 6309

Retainer condition: -

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.: 1.9688

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 1.9689

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Foot/Flange condition: Good Ok

Endbell DE size: 3.375 Foot flatness: **Pass**

Endbell DE insulated?: No

> Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE insulated?: No

Endbell ODE size:

3.378



Conclusion

Component Failure

Cause of Failure

Comments

Bearing change and clean up

Service Tech name: Robert Wiley

Service Tech signature: