

MILLINGTON, TN LITTLE ROCK, AR

Job Information

Job #:	95838				Date:	August 5, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Arauco		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type im
Serial#:	L0010140 EV-5	Model#:	Type: RGZP	
Service Factor:	1.15	Frame:	364T	
Horsepower/kW:	60	Rated RPM:	1775	
Rated Amps:	142.0/70.8	Rated Voltage:	230/460	
Phase:	3	Cycles:	60	
Special design:	No			

nage



Тор

Nameplate

DE

ODE

F1

F2









WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6314
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6210
Bearings Retainer:	No	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 Bearing Make Image

Bearing Retainer Image

Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	Other
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Image:




Water jacket:	N/A
---------------	-----

4

Fan: Ok







Motor Mount Position:	Horizontal/Foc	ot mount		Endbell type:
Missing parts?			Endbell Image:	
J-Box cover	O-rings	J-Box		
HH cover	Glands	None None		0





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Other missing parts



Mechanical Inspection (Continued)

			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection


Number of leads:	9	Terminal Markings		
Length of leads:	16 inch	REF: NEMA St Markings Ident	tds. MG 1-2009, Rev. 1- tified By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Bad	4-Yellow	8-Red	
Lug type:		Connections As F	Received:	
Lug Condition:	Bad		Terminal	Lugs
Lug size:				
Lug Attachment:	_			Carlos and a second

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	image	Winding Therma	I Protection: No	
Winding condition :	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:						
Stator test results:	Salvageable					
Megs incoming:	Good	Surge incoming:	Good	Hi-pot in	coming: Good	
Winding Resistance	Incoming					
Ph	ases A to B	Phases B to C	Phase	s C to A	Resistive imbalance	
Incoming 0.	00	0.00	0.00			
Leads/jur	npers: Ok		Lead	jumper Image. :		All and
If other, leads/jumpers:						1.04
Mechanical In	spection					
Inspect bolt holes and	d fasteners. Valida	te correct fasteners.				

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6314
Shaft runout(TIR-Inbound):	0.002	Bearing ODE Size:	6210

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

_



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good	
Seals DE type:	N/A	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	None	Shaft damage:	ОК	
Seals ODE type:	N/A			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	5.9060	Foot flatness:	Pass	
Endbell DE insulated?:	_		Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.5442	variation)?		
Endbell ODE insulated?:	—			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Bearings showed signs of frosting. Drive end shaft bearing fit is 5 thousands to small. Recommend reconditioning and shaft bearing fit work.

Service Tech name: Chr

Chris Wiley

Service Tech signature:

Chris Elder

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301