

Job Information

Job #: 95847 Date: August 9, 2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Be is Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Reliance Enclosure: Totally Enclosed Enclosure Type image

Non-Ventilated

Serial#: Model#: 00000000

Service Factor: Frame: 324T

Horsepower/kW: 40 Rated RPM: 1775

Rated Amps: 99/49.5 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 6311ZZ

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6311ZZ

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection

Not Available



Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 0 Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: Other Shaft Image:





Brg. Image:



Bushings/sleeves image:

Not Available

Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts

J Box bolts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA

spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings: 1-9

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Lug type: Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Not Not Lug Attachment: — Available Available

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass


Stator type: Factory If other, stator type:

Stator condition: Ground If other, stator condition:

Failure location: Coil head If other, stator failure:

Stator Image: Failure Image





Not

Available



AC Electrical Inspection (Continued)

Winding color: Shiny black Winding image Winding Thermal Protection: Yes

Winding condition: Brittle

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

Mechanical Inspection

If other, leads/jumpers:

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Damaged Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6311

Shaft runout(TIR-Inbound): Bearing ODE Size: 6311

Retainer condition: —

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Undersized

Seals DE type: N/A If DE undersized, amt.: Bad

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 2.1657

Seals ODE condition: Worn Shaft damage: Salvageable

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

4.7250 Good

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 4.7275 Bad Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:



Conclusion

Component Failure

Stator and De bearing De housing fit De shaft bearing fit

Cause of Failure

No lubrication

Comments

Found frosting and moisture corrosion in ode bearing DE bearing was destroyed

Service Tech name: Robert Wiley

Service Tech signature: