

Job Information

Job #: 95853 Date: September 6,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Nabholz Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Serial#:

Manufacturer: Pentagram Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Model#:

Service Factor: Frame:

Horsepower/kW: 3 Rated RPM:

Rated Amps: Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top







Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Insulated:

Inspect bolt holes and fasteners. Validate correct fasteners.

.003

Worn

No

Does the shaft turn freely?: No Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6204

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

Bearing DE Size:

Other

6308

Thermal Protection



Lubrication Type: Oil Thermal Protection device DE: —

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: N/A Grease Cond. DE: New

Grease Amt ODE: N/A Grease Cond. ODE: New

Seals DE type: Isolators Seals Image:

Seals DE size:

Seals DE (inbound) condition : Worn

Seals ODE type: Isolators

Seals ODE size:

Seals ODE (inbound) condition

Worn

Shaft damage cause: None Shaft Image:



Fax 901-873-5301



Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts





Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 —

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6308 C3

Shaft runout(TIR-Inbound): Bearing ODE Size: 6204 C3

Retainer condition: -

Phone 901-873-5300

Fax 901-873-5301



Seals DE condition : Worn Brg. Seats DE: Undersized

Seals DE type: Isolators If DE undersized, amt.: 1.5742

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Isolators

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.5433 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size:

Endbell ODE insulated?: -



Conclusion

Component Failure

D.E. Shaft bearing journal measures too small. Power and sensor cord need to be replaced.

Cause of Failure

Lower seal failure. Power cord severed.

Comments

Motor windings checked good. Power and sensor cord specs: (4C 14AWG) - (5C 18AWG). Approx 35' long. Shaft seal surfaces measure 1.4992 & 1.4992

Service Tech name: Terrence Holland

Service Tech signature: