

MILLINGTON, TN LITTLE ROCK, AR

Job Information

Job #:	95858					August 13, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Mohawk industries		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	ABB	Enclosure :	Totally Enclosed Fan Cooled
Serial#:		Model#:	M3AA 200 MLA6
Service Factor:		Frame:	200MLA
Horsepower/kW:	22	Rated RPM:	1180
Rated Amps:	39	Rated Voltage:	440
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2

ABB Motors CCO







-2

Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Grease
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Cup
Shaft grounding device present?: Type of grounding device:	No	Contaminant Image:	
Shaft runout(TIR-Inbound):	0.001		Transe (The

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	6312
Bearings ODE:	Worn	Bearings ODE make:	NSK
Bearing Type:	Ball	Bearing ODE Size:	6210
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	Other
Seals DE type: Seals DE size: Seals DE (inbound) condition :	Slinger	Seals Image:	
Seals ODE type:	Slinger		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Image:



Water	jacket:	N/A

۱

Fan: Ok



Endbell Image:

Frame cond.: Good



Motor Mount Position:	Horizontal/Foot mount

O-rings

Glands

Endbell type:

Single piece

Other missing parts

Missing parts?

J-Box cover

HH cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

J-Box

None



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:		
Length of leads:	9 inch	REF: NEMA Std Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	F3	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Re	ceived:	
Lug Condition:	_		Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)

Rotor Type:	Cast Aluminum	,		Rotor
Rotor Condition:	Ok	Num rotor bars: 4 Num broken bars: 0	48)	
Rotor Test Results				
Visual: Pass	(Growler: Pass	Single phase:	Pass
Stator type:	Factory	If other, s	stator type:	
Stator condition:	Ok	If other, stato	r condition:	
Failure location:	Other	If other, sta	ator failure:	
Stator Image:				

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding colo	or: Still has color	Winding	g image	Winding Ther	mal Protectior	n: No
Winding condition	1: Solid					
Winding Therm Protection DI						
Winding Therm Protection ODI			And			
Stator test result	s: Salvageable					
Megs incoming:	Good	Surge incoming:	Good	Hi-po	t incoming:	Good
Winding Resistance Incoming						
F	Phases A to B	Phases B to C	Phases	C to A	Resistive	imbalance
Incoming	0.00	0.00	0.00			
Leads/ji	umpers: Ok		Lead	jumper Image	ə. :	
lf other, leads/ji	umpers:					
Mechanical I	nspection					
Inspect bolt holes and fasteners. Validate correct fasteners.						
Shaft	Condition: Good		Bearings	Retainer:	Yes	
Type of groundir	ng device:		Bearing	DE Size:	6312	

Bearing ODE Size:

6210

Shaft runout(TIR-Inbound):

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Retainer condition:

Good



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good	
Seals DE type:	Slinger	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	Worn	Shaft damage:	ОК	
Seals ODE type:	Slinger			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	5.1181	Foot flatness:	Pass	
Endbell DE insulated?:	_	Does Air Gap Meet Cus	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.5433	variation)?		
Endbell ODE insulated?:	_			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

The bearings showed signs of frosting and was excessively greased causing they're to be grease in the windings. Recommend aegis ring.

Service Tech name: 0

Chris Wiley

Service Tech signature:

Ching Miley

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301