

Job Information

Job #:	95921				Date:	September 9, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Future Fuel	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	GE	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type image
Serial#:	Yn64z029	Model#:	5k053t328a	
Service Factor:	1.15	Frame:	L403mpz16	
Horsepower/kW:	75	Rated RPM:	1190	
Rated Amps:	87.2	Rated Voltage:	460	2
Phase:	3	Cycles:	60	
Special design:	Yes			

Nameplate

DE

ODE

F1

F2

Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			
Shaft runout(TIR-Inbound):	0.003		
Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	5216z
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6212z
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Bearing Retainer Image



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	Slinger	Seals Image:	
Seals DE size:	Special		0
Seals DE (inbound) condition :	Good		
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	Other	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket:

N/A

Fan: Ok



Frame cond.: Good



Motor Mount Position:	Vertical Flange mount

O-rings

Glands

Missing parts?

J-Box cover

Other missing parts

HH cover

Endbell type:

Single piece



Endbell Image:





WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

J-Box

V None



Mechanical Inspection (Continued)

Air Gap Mo	eaurements (N/A on Single Piece E	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	3	Terminal Markings:		
Length of leads:	12 inches	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	6 awg	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Worn	4-Yellow	8-Red	
Lug type:	Copper	Connections As Re	ceived:	
Lug Condition:	Bad	٦	Terminal	Lugs
Lug size:	6awg			
Lug Attachment:	_			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Still has color	Winding	g image Wind	ing Thermal Protection	on: No		
Winding condition :	Solid						
Winding Thermal Protection DE:	_						
Winding Thermal Protection ODE:	_						
Stator test results:	Salvageable						
Megs incoming:	Good	Surge incoming:	Good	Hi-pot incoming:	Good		
Winding Resistance	Winding Resistance Incoming						
Pha	ases A to B	Phases B to C	Phases C to	A Resistiv	e imbalance		
Incoming							
Leads/jum If other, leads/jum		onnection	Lead jump	er Image. :	CR		
Mechanical In	spection						
Inspect bolt holes and	l fasteners. Validat	e correct fasteners.		-			
Shaft Co	ondition: Damag	ged	Bearings Reta	iner: Yes			

Damaged	Dearings Hetanier.	103
	Bearing DE Size:	5216z
.003	Bearing ODE Size:	6212z
	Ŭ	

WEST TENNESSEE CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Good

Retainer condition:

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good	
Seals DE type:	Slinger	If DE undersized, amt.:		
Seals DE size:	Special	Brg. Seats ODE:	Undersized	
Seals DE (inbound) condition :		If ODE undersized, amt.:	0.0002	
Seals ODE condition :	None	Shaft damage:	ОК	
Seals ODE type:	N/A			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok	
Endbell DE size:	5.5118	Foot flatness:	Pass	
Endbell DE insulated?:	No		Customer or EASA spec(<10%	
Endbell ODE size:	4.3325	variation)?		
Endbell ODE insulated?:	No	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Shaft, bearings, guide bearing, endbell, leads,

Cause of Failure

Corroded connection, debris in guide bearing

Comments

Service Tech name: Trevor Hall

Service Tech signature:



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301