

Job Information

96088 Job #: Date: October 9, 2019

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: **US Electrics** Enclosure: Totally Enclosed **Enclosure Type image**

Fan Cooled

TYPE:TC Serial#: Model#:

Service Factor: 447t 1.15 Frame:

Horsepower/kW: 200 Rated RPM: 1780

Rated Amps: 228 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top











Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6220.C3

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6313

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

0.001

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: Other Fan: Broken Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☑ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None





Other missing parts

Bolts that hold J-Box on stater are broke at the frame



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 7in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: —





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 68

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6220

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6313

Retainer condition: Good

Fax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Shaft damage: OK None

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Foot/Flange condition: Good Ok

Endbell DE size: 7.0878 Foot flatness: **Pass**

Endbell DE insulated?:

5.5122

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE insulated?:

Endbell ODE size:



Conclusion

Component Failure

Cause of Failure

Comments

Both bearings show signs of frosting. The fan is cracked around shaft fit. The ODE bearing seat on the shaft is undersized. Recommend reconditioning, agius ring, new fan, new bearings, and machine work ont the ODE bearing seat on the shaft.

Charles

Service Tech name: Chris Wiley

Service Tech signature: