

# **Job Information**

| Job #:    | 96103 |                |    |                | Date: | October 28,<br>2019 |
|-----------|-------|----------------|----|----------------|-------|---------------------|
| Priority: | _     | Authorized OT: | No | Authorized by: |       |                     |

# **Customer Information**

| Name:        | Ryerson |                | Reason: |      |
|--------------|---------|----------------|---------|------|
| Contact:     |         | Motor#:        |         | PO#: |
| Application: | _       | Special notes: |         |      |

# **Name Plate Information**

| Manufacturer:   | Baldor | Enclosure :    | Totally Enclosed<br>Fan Cooled |  |
|-----------------|--------|----------------|--------------------------------|--|
| Serial#:        |        | Model#:        |                                |  |
| Service Factor: | 1.15   | Frame:         | 256T                           |  |
| Horsepower/kW:  | 20     | Rated RPM:     | 3600                           |  |
| Rated Amps:     | 46/23  | Rated Voltage: | 230/460                        |  |
| Phase:          | 3      | Cycles:        | 60                             |  |
| Special design: | No     |                |                                |  |

#### Enclosure Type image



Nameplate

DE

ODE

F1

F2



WEST TENNESSEE







CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

 7030 Ryburn Drive
 6812 Li

 Millington, TN 38053
 Little Ro

 Phone 901-873-5300
 Phone 5

 Fax 901-873-5301
 Fax 501

Тор



# **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

| Does the shaft turn freely?:     | Yes            | Contaminant(s):     | None |
|----------------------------------|----------------|---------------------|------|
| Shaft rotation:                  | Bi-directional | Contaminant(s) Amt: | None |
| Shaft grounding device present?: | No             |                     |      |
| Type of grounding device:        |                |                     |      |

Shaft runout(TIR-Inbound):

| Bearings DE:        | Worn | Bearings DE make:        | SKF   |
|---------------------|------|--------------------------|-------|
| Insulated:          | No   | Bearing DE Size:         | 6309  |
| Bearings ODE:       | Worn | Bearings ODE make:       | Other |
| Bearing Type:       | Ball | Bearing ODE Size:        | 3208  |
| Bearings Retainer:  | Yes  | Thermal Protection:      | No    |
| Retainer condition: | Good | Thermal Protection Type: | _     |

#### Bearing Type Image



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Bearing Make Image

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



**Bearing Retainer Image** 



#### **Thermal Protection**



# **Mechanical Inspection (Continued)**

| Lubrication Type:               | Grease  | Thermal Protection device DE:  | _       |
|---------------------------------|---------|--------------------------------|---------|
| Lubrication brand inbound:      | Unknown | Thermal Protection device ODE: | _       |
| Lubrication brand outbound:     | Unknown |                                |         |
| Grease Amt DE:                  | 1/4     | Grease Cond. DE:               | Charred |
| Grease Amt ODE:                 | 1/4     | Grease Cond. ODE:              | Charred |
|                                 |         |                                |         |
| Seals DE type:                  | N/A     |                                |         |
| Seals DE size:                  |         |                                |         |
| Seals DE (inbound) condition :  |         |                                |         |
|                                 |         |                                |         |
| Seals ODE type:                 | N/A     |                                |         |
| Seals ODE size:                 |         |                                |         |
| Seals ODE (inbound) condition : |         |                                |         |
| Shaft damage cause:             | None    | Shaft Image:                   |         |



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection (Continued)**

Brg. Image:



| Water j | acket: | N/A |
|---------|--------|-----|
|---------|--------|-----|

Fan: Ok



Endbell Image:

Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

O-rings

Glands

J-Box

**V** None

Endbell type:

Single piece

Other missing parts

Missing parts?

J-Box cover

HH cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

| Air Gap Meaurements (N/A on Single Pie | Does Air Gap Meet Customer or EASA spec(<10% variation)? |   |
|--|--|---|
| DE @ 0                                 | ODE @ 0  | _ |
| DE @ 90                                | ODE @ 90   |   |
| DE @ 180                               | ODE @ 180  |   |
| DE @ 270                               | ODE @ 270  |   |


# **AC Electrical Inspection**

| Number of leads: | 9     | Terminal Markings:               | :   |                                  |
|------------------|-------|----------------------------------|---|----------------------------------|
| Length of leads: | 10 in | REF: NEMA Ste<br>Markings Identi | ds. MG 1-2009, Rev. 1-<br>ified By Color:             | 2010, 2.41-Terminal              |
| Size of leads:   |       | 1-Blue<br>2-White<br>3-Orange    | 5-Black<br>6-No color assigned<br>7-No color assigned | P1-No color assigned<br>P2-Brown |
| Lead condition:  | Good  | 4-Yellow                         | 8-Red   |                                  |
| Lug type:        | NA    | Connections As R                 | eceived:  |                                  |
| Lug Condition:   | _     |                                  | Terminal  | Lugs                             |
| Lug size:        |       |                                  |   |                                  |
| Lug Attachment:  | _     |                                  |   |                                  |

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

| Winding color:                     | Still has color      | Winding              | image W  | Vinding Thermal | Protection: Yes     |
|------------------------------------|----------------------|----------------------|----------|-----------------|---------------------|
| Winding condition :                | Solid                |                      |          |                 |                     |
| Winding Thermal<br>Protection DE:  |                      |                      |          |                 |                     |
| Winding Thermal<br>Protection ODE: |                      |                      |          |                 |                     |
| Stator test results:               | Salvageable          |                      |          |                 |                     |
| Megs incoming:                     | Good                 | Surge incoming:      | Good     | Hi-pot inc      | coming: Good        |
| Winding Resistance                 | Incoming             |                      |          |                 |                     |
| Ph                                 | ases A to B          | Phases B to C        | Phases ( | C to A          | Resistive imbalance |
| Incoming 0.                        | .00                  | 0.00                 | 0.00     |                 |                     |
| Leads/jur                          | npers: Ok            |                      | Lead ju  | umper Image. :  |                     |
| lf other, leads/jur                | npers:               |                      |          |                 |                     |
| Mechanical In                      | spection             |                      |          |                 | -                   |
| Inspect bolt holes and             | d fasteners. Validat | e correct fasteners. |          |                 |                     |

| Shaft Condition:           | Good  | Bearings Retainer: | Yes  |
|----------------------------|-------|--------------------|------|
| Type of grounding device:  |       | Bearing DE Size:   | 6309 |
| Shaft runout(TIR-Inbound): | 0.001 | Bearing ODE Size:  | 6208 |

WEST TENNESSEE CENTRAL ARKANSAS 7030 Ryburn Drive 6812 Lindsey Rd.

Retainer condition:

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Good



# **Mechanical Inspection (Continued)**

| Seals DE condition :            | None   | Brg. Seats DE:           | Good                     |
|---------------------------------|--------|--------------------------|--------------------------|
| Seals DE type:                  | N/A    | If DE undersized, amt.:  |                          |
| Seals DE size:                  |        | Brg. Seats ODE:          | Good                     |
| Seals DE (inbound) condition :  |        | If ODE undersized, amt.: |                          |
| Seals ODE condition :           | None   | Shaft damage:            | ОК                       |
| Seals ODE type:                 | N/A    |                          |                          |
| Seals ODE size:                 |        | Bushings/sleeves DE:     | Ok                       |
| Seals ODE (inbound) condition : |        | Bushings/sleeves ODE:    | Ok                       |
| Endbell fits/damage:            | Good   | Foot/Flange condition:   | Ok                       |
| Endbell DE size:                | 3.9377 | Foot flatness:           | Pass                     |
| Endbell DE insulated?:          | _      |                          | stomer or EASA spec(<10% |
| Endbell ODE size:               | 3.1501 | variation)?              |                          |
| Endbell ODE insulated?:         | _      |                          |                          |

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## Conclusion

**Component Failure** 

**Cause of Failure** 

Comments

Both bearings show signs of wear. Recommend new bearings and a reconditioning

Service Tech name: Ch

Chris Wiley

Service Tech signature:

Christeling

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301