

Job Information

Job #: 96135 Date: October 24,

2019

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Advanced fluids technologies Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

355

No

Serial#:

Manufacturer: Barter varnost Enclosure: Totally Enclosed Enclosure Type image

Model#:

Fan Cooled

Service Factor: 1.15 Frame:

Horsepower/kW: 26 Rated RPM: 3525

Rated Amps: 71 Rated Voltage: 278/480

Phase: 3 Cycles: 60

Nameplate DE ODE F1 F2 Top



Special design:







Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6310

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6310

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Other Seals Image:

Seals DE size: 50-70-8

Seals DE (inbound) condition: Bad

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.:





Good

Endbell type: Motor Mount Position: Horizontal/Foot mount Single piece

Missing parts? Endbell Image:

☐ J-Box ☐ J-Box cover O-rings

✓ None ☐ HH cover Glands

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 6 Terminal Markings:

Length of leads: 4 in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Failure Image:





AC Electrical Inspection (Continued)

Winding color: Painted Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Surge incoming: Hi-pot incoming: Good Good Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

> Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6310

Shaft runout(TIR-Inbound): Bearing ODE Size: 0.001 6310

Retainer condition: Good

hone 901-873-5300 Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Other If DE undersized, amt.:

Seals DE size: 50-70-8 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3315 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:

4.3310



Conclusion

Component Failure

Cause of Failure

Comments

Both bearings show signs of wear and the DE seal is worn. Recommend new bearings and new seal

Service Tech name: Chris Wiley

Service Tech signature: