

Job Information

Job #:	96305				Date:	December 17, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Arauco		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled
Serial#:		Model#:	
Service Factor:	1.15	Frame:	362T
Horsepower/kW:	60	Rated RPM:	1775
Rated Amps:	133.4/66.7	Rated Voltage:	230/460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image





DE

F2

Тор



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



ODE

F1



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Grease
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

Bearings DE:	Worn	Bearings DE make:	SKF
Insulated:	No	Bearing DE Size:	6313-2RS
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6313-2RS
Bearings Retainer:	No	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image

nage Bearli

Bearing Retainer Image

Thermal Protection



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	Other
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water	jacket:	N/A

Fan: Ok



Frame cond.: Good



Single piece

Motor Mount Position:	Horizontal/Fo	pot mount		Endbell type:
Missing parts?			Endbell Image:	
J-Box cover	O-rings	J-Box		
HH cover	Glands	None None		
Other missing parts				
2 J-box mount bolts	are missing			



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap M	eaurements (N/A on Single Piece E	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	3	Terminal Markings:		
Length of leads:	13 in	REF: NEMA Sto Markings Identif	ls. MG 1-2009, Rev. 1- ïed By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Re	eceived:	
Lug Condition:	Good		Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



6313

6313

AC Electrical Inspection (Continued)

Winding colo	r: Like ne	w Windin	g image Winding	Thermal Protection: No
Winding condition	: Solid		Amer C	
Winding Therma Protection DE				
Winding Therma Protection ODE				
Stator test results	s: Salvage	eable		
Megs incoming:	Good	Surge incoming:	Good H	Hi-pot incoming: Good
Winding Resistanc	e Incoming			
Р	hases A to B	Phases B to C	Phases C to A	Resistive imbalance
Incoming	0.00	0.00	0.00	
Leads/ju	umpers: C	Dk	Lead jumper l	mage. :
lf other, leads/ju	impers:			
Mechanical I	nspectio	n		
Inspect bolt holes a	nd fasteners.	Validate correct fasteners.		
Shaft (Condition:	Good	Bearings Retainer	r: No

Type of grounding device:Bearing DE Size:Shaft runout(TIR-Inbound):Bearing ODE Size:

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.5137 BAD	Foot flatness:	Pass
Endbell DE insulated?:	_	Does Air Gap Meet Cus	tomer or EASA spec(<10%
Endbell ODE size:	5.5118 GOOD	variation)?	
Endbell ODE insulated?:	_	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Both bearings show normal signs of wear, missing two J-Box mount bolts, and the DE end bell is over sized. Recommend reconditioning, new bearings, two new bolts and machine work on the DE end bell.

Service Tech name: Chr

Chris Wiley

Service Tech signature:

Azisteliy

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301