

Job Information

Job #:	96328				Date:	December 11, 2019
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Greenbrier central		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Demagogue	Enclosure :	Open Drop Proof (ODP)	Enclos	Enclosure Type image	
Serial#:		Model#:	()		8	
Service Factor:		Frame:		1		
Horsepower/kW:		Rated RPM:				
Rated Amps:		Rated Voltage:	460		The second se	
Phase:	3	Cycles:	60			
Special design:	No					
Nameplate	DE	ODE	F1	F2	Тор	



VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	62072zhtf1
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6206
Bearings Retainer:	No	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	Thermocouple

Bearing Retainer Image

Bearing Type Image



Bearing Make Image



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	0	Grease Cond. DE:	Other
Grease Amt ODE:	0	Grease Cond. ODE:	Other
Seals DE type:	Isolators	Seals Image:	
Seals DE size:	35x52x7		
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Frame cond.:

Mechanical Inspection (Continued)

Brg. Image:

Water jacket:



N/A	Fan:	N/A



Good

Motor Mount Position:
Horizontal/Flange mount
Endbell Image:
Single piece

Missing parts?
Endbell Image:
Endbell Image:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)


Air Gap Meaurements (N/A on Single Piece Endbell)			Does Air Gap Meet Customer or EASA spec(<10% variation)?
	DE @ 0	ODE @ 0	_
	DE @ 90	ODE @ 90	
	DE @ 180	ODE @ 180	
	DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:		
Length of leads:	8"	REF: NEMA Stds Markings Identifi	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	16	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:	Copper	Connections As Rea	ceived:	
Lug Condition:	Good	ſ	Terminal	Lugs
Lug size:	Same			
Lug Attachment:	-			



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Dull black	Winding	g image	Winding Therma	Il Protection:	Yes
Winding condition :	Solid				8	
Winding Thermal Protection DE:	Good		Mare -			
Winding Thermal Protection ODE:	_				See 1	
Stator test results:	Rewind					
Megs incoming: Gc	ood	Surge incoming:	Good	Hi-pot in	coming: (Good
Winding Resistance In	coming					
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive im	balance
Incoming						
Leads/jumpe	ers: Ok					
If other, leads/jumpe	ers:					

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	No
Type of grounding device:		Bearing DE Size:	62072zhtf1
Shaft runout(TIR-Inbound):	.001	Bearing ODE Size:	62062z

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Slinger	If DE undersized, amt.:	
Seals DE size:	35x52x7	Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	2.8347	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Cu	stomer or EASA spec(<10%
Endbell ODE size:	2.4412	variation)?	
Endbell ODE insulated?:	No	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Windings

Cause of Failure

Overloading windings. Too much heat

Comments

Service Tech name: Trevor Hall

Service Tech signature:

1 - JUN

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301