

Job Information

96330 Job #: Date: December 19,

2019

Priority: Authorized OT: No Authorized by:

Customer Information

Name: **WELSPUN** Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Serial#:

Manufacturer: US Enclosure: Open Drop Proof **Enclosure Type image**

(ODP)

Model#:

Service Factor: 1.15 Frame: H444tp

Horsepower/kW: 150 Rated RPM: 1780

Rated Amps: 164 Rated Voltage: 460

Cycles: Phase: 3 60

Special design:

No

Nameplate DE ODE F1 F2 Top















Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: CCW Contaminant(s) Amt: None

Shaft grounding device

present?:

Yes

Type of grounding device: Aegis

Shaft runout(TIR-Inbound): Good

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 7322bxlmpua254rj0101

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 62152zc3gjn224l

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: Thermocouple

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Oil Thermal Protection device DE: Good

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: Charred

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Vertical Flange mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts

Fill hole plug







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Good

4 awg

Lead condition:

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 18"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 4 awg

P2-Brown 2-White 6-No color assigned

3-Orange 7-No color assigned 4-Yellow 8-Red

Connections As Received: 1,7. 2,8. 3,9

Coppe Lug type:

Lug Condition: Good Terminal Lugs



Lug size:

Lug Attachment:

Failure Image:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 57

Num broken bars: 0

Rotor



Rotor Test Results

Stator Image:

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Open If other, stator condition:

Failure location: Coil head If other, stator failure:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Good Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Bad Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Aegis ring Bearing DE Size: 7322b

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6215 2z

Retainer condition: Good

ax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 9.4499 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

5.1190



Conclusion

Component Failure

Bearings, windings

Cause of Failure

Comments

Service Tech name: Trevor Hall

Service Tech signature:

/~m//