

### **Job Information**

Job #: 96410 Date: January 6, 2020

Priority: — Authorized OT: No Authorized by:

## **Customer Information**

Name: 3M Company Reason:

Contact: Motor#: PO#:

Application: – Special notes:

### **Name Plate Information**

Manufacturer: Siemens Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: J06T2010ES1 Model#:

Service Factor: 1.15 Frame: B449T

Horsepower/kW: 250 Rated RPM: 1185

Rated Amps: 280 Rated Voltage: 460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







WEST TENNESSEE



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Grease

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?:

Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6314

Bearings ODE: Fell Apart Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6210

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Hard

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: Broken Frame cond.: Good





Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☑ J-Box cover ☐ O-rings

**✓** J-Box

☐ HH cover ☐ Glands ☐

☐ None

Other missing parts





Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

## **AC Electrical Inspection**

Number of leads: 9 Terminal Markings:

Length of leads: 14 1/2 in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Lug type: NA Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Dull black Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6314

Shaft runout(TIR-Inbound): Bearing ODE Size: 6210

Retainer condition: —

Fax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 5.9078 Foot flatness: Pass

Endbell DE insulated?: —

3.5448

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:



#### Conclusion

**Component Failure** 

**Cause of Failure** 

#### **Comments**

DE bearing shows signs of frosting, ODE bearing shows signs of extensive wear, ODE bearing fit on shaft is worn, DE and ODE bearing fits in the end bells are over sized, fan is broke, the J-box is missing, and the windings are blown. Recommend reconditioning, new bearings, aegis ring, machine work on DE and ODE end bells, machine work on ODE bearing fit of the shaft, new fan, new J-box, and rewind.

Choix Willy

Service Tech name: Chris Wiley

Service Tech signature: