

Job Information

Job #:	96485				Date:	January 27, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	AFT		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	BARTEC	Enclosure :	Totally Enclosed Fan Cooled	Enclosure Type image
Serial#:	200941670	Model#:	3KTC180M-2	
Service Factor:		Frame:	180M	
Horsepower/kW:	26KW	Rated RPM:	3525	
Rated Amps:		Rated Voltage:	480	
Phase:	3	Cycles:	60	
Special design:	No			

Nameplate

DE

ODE

F1

F2



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301







Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

FAG	Bearings DE make:	Bearings DE:
6310	Bearing DE Size:	Insulated:
FAG	Bearings ODE make:	Bearings ODE:
6310	Bearing ODE Size:	Bearing Type:
Yes	Thermal Protection:	Bearings Retainer:
_	Thermal Protection Type:	Retainer condition:

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

nemiai Fiolection Type.

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type: Seals DE size: Seals DE (inbound) condition :	Isolators 50 72 8 Good	Seals Image:	
Seals ODE type: Seals ODE size: Seals ODE (inbound) condition :	Isolators 50 72 8 Good	Seals Image 2:	



Shaft Image:

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Shaft damage cause:

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

None



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan: Ok



Frame cond.: Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Endbell Image: J-Box O-rings **N**one Glands

Other missing parts

Missing parts?

J-Box cover

HH cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301









Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	6	Terminal Markings:	
Length of leads:		REF: NEMA Stds. MG 1-2009, Rev. 1- Markings Identified By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue5-Black2-White6-No color assigned3-Orange7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow 8-Red	
Lug type:		Connections As Received: 480	
Lug Condition:	Good	Terminal	Lugs
Lug size:			
Lug Attachment:	_		6337

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Winding	g image N	Winding Thermal P	Protection: Yes
Winding condition :	Solid				T-1-C WINCING ANALYZEI Discussion
Winding Thermal Protection DE:					
Winding Thermal Protection ODE:		7.	reitt		
Stator test results:	Salvageable				
Megs incoming:	Good	Surge incoming:	Good	Hi-pot inco	ming: Good
Winding Resistance	Incoming				
Ph	ases A to B	Phases B to C	Phases	C to A R	Resistive imbalance
Incoming 0.	00	0.00	0.00	(0.00
Leads/jun	npers: Ok		Lead j	umper Image. :	605
If other, leads/jumpers:					
Mechanical In	spection				
Inspect bolt holes and	d fasteners. Validat	te correct fasteners.			

Shaft Condition:GoodBearings Retainer:YesType of grounding device:Bearing DE Size:6310Shaft runout(TIR-Inbound):Bearing ODE Size:6310

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	Isolators	If DE undersized, amt.:	1.9689
Seals DE size:	50 72 8	Brg. Seats ODE:	Good
Seals DE (inbound) condition :	Good	If ODE undersized, amt.:	1.9690
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	Isolators		
Seals ODE size:	50 72 8	Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :	Good	Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.3309	Foot flatness:	Pass
Endbell DE insulated?:	No	Does Air Gap Meet Cust	stomer or EASA spec(<10%
Endbell ODE size:	4.3312	variation)?	
Endbell ODE insulated?:	No	_	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

New ageis ring and bearings.Found Frosting in ODE BEARING

Service Tech name:

Robert Wiley

Service Tech signature:

es Dilor

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301