

Job Information

Job #:	96542)6542				
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Arauco		Reason:		
Contact:		Motor#:		PO#:	
Application:	_	Special notes:			

Name Plate Information

Manufacturer:	Manufacturer: Baldor		Totally Enclosed Fan Cooled
Serial#:	C17060208	Model#:	
Service Factor:	1.15	Frame:	326TSC
Horsepower/kW:	50	Rated RPM:	3540
Rated Amps:	112/56	Rated Voltage:	230/460
Phase:	3	Cycles:	60

Enclosure Type image



Nameplate

Special design:

DE

No

ODE

F1

F2

Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	
Insulated:	No	Bearing DE Size:	7312
Bearings ODE:	Worn	Bearings ODE make:	SKF
Bearing Type:	Ball	Bearing ODE Size:	6311
Bearings Retainer:	Yes	Thermal Protection:	No
Retainer condition:	Good	Thermal Protection Type:	_

Bearing Type Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Thermal Protection



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	—
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	Other
Grease Amt ODE:	Full	Grease Cond. ODE:	Other
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Brg. Image:



Water	jacket:	N/A
-------	---------	-----

Fan: Ok



Frame cond.: Good



Single piece

Motor Mount Position: Horizontal/Foot mount Missing parts? Endbell Image: J-Box J-Box cover O-rings HH cover None Glands



Endbell type:



Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Singl	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection


Number of leads:	9	Terminal Markings:				
Length of leads:	9in	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:				
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown		
Lead condition:	Good	4-Yellow	8-Red			
Lug type:		Connections As Re	eceived:			
Lug Condition:	Good		Terminal	Lugs		
Lug size:						
Lug Attachment:	-					

WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding cold	or:	Like new	Winding	j image	Winding Therr	mal Protection	: No	
Winding condition : Solid								
Winding Therm Protection DI		_						
Winding Therm Protection ODI		_						
Stator test result	ts:	Rewind						
Megs incoming:	Go	ood	Surge incoming:	Good	Hi-pot	t incoming:	Good	
Winding Resistand	ce Ind	coming						
F	Phase	es A to B	Phases B to C	Phase	es C to A	Resistive	imbalance	
Incoming	0.00		0.00	0.00				
Leads/j	jumpe	ers: Ok		Lea	d jumper Image	e. :		
lf other, leads/j	jumpe	ers:						
Mechanical Inspection								
Inspect bolt holes a	and fa	steners. Validat	te correct fasteners.				Ban In Street	
Shaft	Cond	lition: Good		Bearing	s Retainer:	Yes		

Type of grounding device:

Shaft runout(TIR-Inbound):

Retainer condition:

: Good

Bearing DE Size: 7312 Bearing ODE Size: 6311

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



MILLINGTON, TN LITTLE ROCK, AR

Mechanical Inspection (Continued)

Seals DE condition :	None	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	
Seals ODE condition :	None	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	5.1185	Foot flatness:	Pass
Endbell DE insulated?:	_		stomer or EASA spec(<10%
Endbell ODE size:	variation Endbell ODE size: 4.7251		
Endbell ODE insulated?:	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Windings test show short to ground, DE bearing shows signs of wear, ODE bearing shows signs of frosting, and the Jbox is missing. Recommend reconditioning, new bearings, new J-box, rewind, and a agies ring.

Service Tech name: Chr

Chris Wiley

Service Tech signature:

Char Chilup

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301