

Job Information

Job #:	96581				Date:	February 25, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Sage V Foods		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

No

Manufacturer:	Fimet	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	809600860	Model#:	
Service Factor:	1.15	Frame:	180m
Horsepower/kW:	22kw	Rated RPM:	1760
Rated Amps:	24.5/37	Rated Voltage:	760-830Y/440-48
Phase:	3	Cycles:	60

Enclosure Type image



Nameplate

IMIET) Synchr

Special design:

DE

ODE

F1

F2

Тор



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	Other
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			And in

Bearings DE:	Fell Apart	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	6310Z
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6309Z
Bearings Retainer:	No	Thermal Protection:	No
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image

Bearing Retainer Image

Thermal Protection



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	0	Grease Cond. DE:	Charred
Grease Amt ODE:	1/4	Grease Cond. ODE:	Charred
Seals DE type:	Slinger		
Seals DE size:	50-65-8		
Seals DE (inbound) condition :	Bad		
Seals ODE type:	Slinger		
Seals ODE size:	45-62-8		
Seals ODE (inbound) condition :	Bad		
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Water jacket: N/A Fan: Broken Frame cond.: Good Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece Missing parts? Endbell Image: J-Box cover O-rings J-Box HH cover None Glands Other missing parts Bolt for fan cover

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	6	Terminal Markings:			
Length of leads:	7in	REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Markings Identified By Color:			
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown	
Lead condition:	Worn	4-Yellow	8-Red		
Lug type:		Connections As Re	eceived:		
Lug Condition:	_		Terminal	Lugs	
Lug size:					
Lug Attachment:	_				

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053

Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Painted	Winding	g image	Winding Therma	al Protection	: Yes
Winding condition :	Solid					
Winding Thermal Protection DE:						
Winding Thermal Protection ODE:						
Stator test results:	Rewind					
Megs incoming:	Good	Surge incoming:	Good	Hi-pot ir	ncoming:	Good
Winding Resistance	Incoming					
Ph	ases A to B	Phases B to C	Phases	C to A	Resistive	imbalance
Incoming 0.	.00	0.00	0.00			
Leads/jur	npers: Ok		Lead	jumper Image.		
If other, leads/jur	npers:					
Mechanical Inspection						
Inspect bolt holes and	d fasteners. Valida	te correct fasteners.				
Shaft C	ondition: Good		Bearings	Retainer: N	lo	

Type of grounding device:Bearing DE Size:6310Shaft runout(TIR-Inbound):Bearing ODE Size:6309

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good	
Seals DE type:	Slinger	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	Worn	Shaft damage:	ОК	
Seals ODE type:	Slinger			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok	
Endbell DE size:	4.3326	Foot flatness:	Pass	
Endbell DE insulated?:	Endbell DE insulated?: —		stomer or EASA spec(<10%	
Endbell ODE size:	3.9389	variation)?		
Endbell ODE insulated?:	_	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

DE bearing wiped out throwing metal into the windings, ODE bearing shows sings of frostings, DE and ODE bearing fits on shaft and in the end bells are bad, J-box is broke the J-box mounts on the stater are broke, seals are bad, fan is broke, and a bolt for the fan cover is missing. Recommend machine work, rewind, new bearings, new seals, aegis ring, new fan, new J-box, and a bolt for the fan cover.

Service Tech name: Chris Wiley

Service Tech signature:

Mar Chilud

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301