

Job Information

Job #:	96586					March 3, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	Process and Power		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Baldor	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	A1905152081	Model#:	
Service Factor:	1.15	Frame:	449TDZ
Horsepower/kW:	250	Rated RPM:	1785
Rated Amps:	278	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1

F2





Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301







Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	No	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	SKF	
Insulated:	No	Bearing DE Size:	NU222	
Bearings ODE:	Worn	Bearings ODE make:	SKF	
Bearing Type:	Ball	Bearing ODE Size:	6318	
Bearings Retainer:	Yes	Thermal Protection:	Yes	
Retainer condition:	_	Thermal Protection Type:	_	

Bearing Type Image



Bearing Make Image



WEST TENNESSEE CI 7030 Ryburn Drive 68 Millington, TN 38053 Litt Phone 901-873-5300 Ph Fax 901-873-5301 Fa

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

_	Thermal Protection device DE:	Grease	Lubrication Type:
_	Thermal Protection device ODE:	Unknown	Lubrication brand inbound:
		Unknown	Lubrication brand outbound:
New	Grease Cond. DE:	0	Grease Amt DE:
New	Grease Cond. ODE:	Full	Grease Amt ODE:
	Seals Image:	Slinger	Seals DE type: Seals DE size:
		Bad	Seals DE (inbound) condition :
	Seals Image 2:	Slinger	Seals ODE type:
			Seals ODE size:
			Seals ODE (inbound) condition :
	Shaft Image:	None	Shaft damage cause:



WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301




Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket: Ok



Fan: Ok



Endbell Image:

Frame cond.: Good



Motor Mount Position:

Missing parts?

J-Box cover

HH cover

Horizontal/Foot mount

O-rings

Glands

J-Box

None

Endbell type:

Single piece

Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)


Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

AC Electrical Inspection

Number of leads:	6	Terminal Markings:	1-6	
Length of leads:	6'6"	REF: NEMA Stds Markings Identifie	s. MG 1-2009, Rev. 1- ed By Color:	2010, 2.41-Terminal
Size of leads:	2/0	1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Red	ceived:	
Lug Condition:	Good	Т	erminal	Lugs
Lug size:				
Lug Attachment:	_			



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding color:	Like new	Windin	g image	Winding The	rmal Protection:	Yes	
Winding condition :	Solid						
Winding Thermal Protection DE:	_	6. A.					
Winding Thermal Protection ODE:	_		57				
Stator test results:	Rewind						
Megs incoming: Ba	ad	Surge incoming:	Bad	Hi-pc	ot incoming:	Bad	
Winding Resistance In	Winding Resistance Incoming						
Phase	es A to B	Phases B to C	Phase	es C to A	Resistive i	mbalance	
Incoming 0.00		0.00	0.00		0.00		
Leads/jumpe	ers: Ok		Lea	d jumper Imag	e. :		
If other, leads/jumpe	ers:						
Mechanical Ins	Mechanical Inspection						
Inspect bolt holes and fa	asteners. Valida	ate correct fasteners.					
Shaft Conc	dition: Othe	r	Bearing	s Retainer:	Yes		
Type of grounding de	evice:		Bearir	ng DE Size:	NU222		

Bearing ODE Size:

6318

Shaft runout(TIR-Inbound):

7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Retainer condition: Bad

CENTRAL ARKANSAS WEST TENNESSEE 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

.005



Mechanical Inspection (Continued)

Seals DE condition :	Other	Brg. Seats DE:	Good	
Seals DE type:	Other	If DE undersized, amt.:	4.3313	
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :	Bad	If ODE undersized, amt.:	3.5438	
Seals ODE condition :	Worn	Shaft damage:	Replace	
Seals ODE type:	Slinger			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Bad	Foot/Flange condition:	Ok	
Endbell DE size:	7.8761	Foot flatness:	Pass	
Endbell DE insulated?:	No		tomer or EASA spec(<10%	
Endbell ODE size:	7.4830	variation)?		
Endbell ODE insulated?:	No			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

De seal and seal cap bad DE and Ode bearing housing fit bad De shaft opening bad needs to be fixed DE bearing cap needs to be bored and sleeved shaft bent over .005 needs to be replaced

Service Tech name:

Robert Wiley

Service Tech signature:

Joss Wiler

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301