

#### **Job Information**

Job #: 96591 Date: February 28,

2020

Priority: — Authorized OT: No Authorized by:

#### **Customer Information**

Name: Dillard's Department Store Reason:

Contact: Motor#: PO#:

Application: – Special notes:

## **Name Plate Information**

Manufacturer: Montgomery Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: GY16007 Model#: 1116600310

Service Factor: 1.5 Frame: P234UP

Horsepower/kW: 15 Rated RPM: 900

Rated Amps: 48/24 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top









WEST TENNESSEE



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Other

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: Other

Insulated: No Bearing DE Size: 6309

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6309

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Other

Grease Amt ODE: Full Grease Cond. ODE: Other

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.: Good



Endbell type: Single piece

Missing parts? Endbell Image:

Horizontal/Foot mount

☐ J-Box cover

Motor Mount Position:

O-rings

☐ J-Box

☐ HH cover

Glands

**✓** None

Other missing parts







#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

### **AC Electrical Inspection**

Number of leads: 9 Terminal Markings:

Length of leads: 9in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: F3 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Lug type: NA Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6309

Shaft runout(TIR-Inbound): Bearing ODE Size: 6309

Retainer condition: Good

7030 Ryburn Drive Millington, TN 38053

hone 901-873-5300

ax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 3.9387 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:

3.9384



#### Conclusion

**Component Failure** 

**Cause of Failure** 

#### **Comments**

Windings are shorted, brake hub is severely worn, both end bells bearing fits are over sized, both bearings show signs of contamination. Recommend rewind, new bearings, machine work on both end bells, and new brake hub.

Chub Island

Service Tech name: Chris Wiley

Service Tech signature: