

Job Information

Job #: 96630 Date: March 6, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Ring Container Technologies Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Tosbiba Enclosure: Open Drop Proof Enclosure Type image

(ODP)

Serial#: 051002422 Model#: BX100-2541-460

Service Factor: 1.15 Frame: 447TZ

Horsepower/kW: 250 Rated RPM: 1770

Rated Amps: 285 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top









WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Contaminant(s): Other Yes

> Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device No

Contaminant Image: present?:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: Koyo

Insulated: Bearing DE Size: 318 ROLLER No

Bearings ODE: Worn Bearings ODE make: NTN

Bearing Type: Bearing ODE Size: 6318 C3 BALL Ball

BEARING

Bearings Retainer: Thermal Protection: Yes No

Retainer condition: Good Thermal Protection Type:

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Charred

Grease Amt ODE: Full Grease Cond. ODE: Other

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

Length of leads: 16 in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: F1 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: Good Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 58

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 318

Shaft runout(TIR-Inbound): Bearing ODE Size: 6318

Retainer condition: Good

ax 901-873-5301



Seals DE condition : None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

7.4820 BAD

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 7.4614 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:



Conclusion

Component Failure

Cause of Failure

Comments

DE bearing show signs of frosting, ODE bearing shows normal signs of wear, and ODE end bell is over sized. Recommend new bearings, aegis ring, machine work, and reconditioning

Cha Eliky

Service Tech name: Chris Wiley

Service Tech signature: