

Job Information

96635 Job #: Date: March 9, 2020

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Synovos Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: **TECO** Enclosure: Open Drop Proof **Enclosure Type image**

(ODP)

Serial#: HT788151003 Model#:

Service Factor: 326T 1.15 Frame:

Horsepower/kW: 50 Rated RPM: 1775

Rated Amps: 117/58.3 Rated Voltage: 230/460

Phase: Cycles: 3 60

Special design:

No

Nameplate DE ODE F1 F2 Top













WEST TENNESSEE



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?: No Contaminant Image:

Shaft runout(TIR-Inbound):

Type of grounding device:

Bearings DE: Worn Bearings DE make: NSK

Insulated: No Bearing DE Size: 6213

Bearings ODE: Worn Bearings ODE make: NSK

Bearing Type: Ball Bearing ODE Size: 6213

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Seals Image 2:



Mechanical Inspection (Continued)

Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Slinger Seals Image:

Seals DE size:

Seals DE (inbound) condition:

Seals ODE (inbound) condition

Seals ODE type: Slinger

Seals ODE size:

:

Shaft damage cause: None Shaft Image:

Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:



Bushings/sleeves image:



Water jacket:

Ok



Fan:

Ok

Frame cond.:

Good



Endbell type:

Single piece

Missing parts?

☐ J-Box cover

Motor Mount Position:

O-rings

☐ J-Box

☐ HH cover

Glands

✓ None

Horizontal/Foot mount

Endbell Image:





Other missing parts



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90**

DE @ 180 ODE @ 180

DE @ 270 **ODE @ 270**

AC Electrical Inspection

Number of leads: 12 Terminal Markings: 1-12

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 12"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 10

P2-Brown 2-White 6-No color assigned

7-No color assigned 3-Orange

4-Yellow 8-Red Lead condition: Good

Connections As Received: High voltage

Lug Condition: Good Terminal Lugs

Lug size:

Lug type:

Lug Attachment:



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Rotor Condition: Ok

Num rotor bars:

Num broken bars:

Rotor



Rotor Test Results

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6213

Shaft runout(TIR-Inbound): Bearing ODE Size: 6213

Retainer condition: —

ax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.: 2.5595

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.: 2.5592

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.7253 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE size: 4.7251

Endbell ODE insulated?: No

CENTRAL ARKANSAS



Conclusion

Component Failure

Cause of Failure

Comments

Wash and bake new bearings Ageis ring .. Found flutting in ode bearing

Service Tech name: Robert Wiley

Service Tech signature: