

### MILLINGTON, TN LITTLE ROCK, AR

## **Job Information**

Job #:	96669				Date:	March 17, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

### **Customer Information**

Name:	Name: Arauco		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

## **Name Plate Information**

Manufacturer:	Siemens	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	L0010140 EV-5	Model#:	TYPE:RGZP
Service Factor:	1.15	Frame:	364T
Horsepower/kW:	60	Rated RPM:	1775
Rated Amps:	142.0/70.8	Rated Voltage:	230/460
Phase:	3	Cycles:	60

#### Enclosure Type image



Nameplate

Special design:

DE

No

ODE

1

F2



Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

F1



## **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	Carbon
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	Other
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			
Shaft runout(TIR-Inbound):			

1

#### Bearing Type Image

Bearing Make Image

Bearing Retainer Image

**Thermal Protection** 



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	Slinger		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## MILLINGTON, TN LITTLE ROCK, AR

#### **Mechanical Inspection (Continued)**

Water jacket: N/A Fan: Ok Frame cond.: Good Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece Missing parts? Endbell Image: O-rings J-Box J-Box cover **N**one HH cover Glands Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

# **AC Electrical Inspection**


Number of leads:	9	Terminal Markings:		
Length of leads:	15in	REF: NEMA Sto Markings Identif	ds. MG 1-2009, Rev. 1- fied By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Bad	4-Yellow	8-Red	
Lug type:		Connections As Re	eceived:	
Lug Condition:	_		Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## MILLINGTON, TN LITTLE ROCK, AR

#### **AC Electrical Inspection (Continued)**



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Winding color	: Dull black	Winding	image \	Winding Therma	l Protection: No
Winding condition	: Solid				
Winding Therma Protection DE					
Winding Therma Protection ODE					
Stator test results	: Rewind				
Megs incoming:	Good	Surge incoming:	Good	Hi-pot in	coming: Good
Winding Resistance	e Incoming				
Pł	nases A to B	Phases B to C	Phases	C to A	Resistive imbalance
Incoming 0	.00	0.00	0.00		
Leads/ju	mpers: Open		Lead	jumper Image. :	
If other, leads/ju	mpers:				
Mechanical Ir	nspection				
Inspect bolt holes an	d fasteners. Validat	te correct fasteners.			

Shaft Condition:	Good	Bearings Retainer:	No
Type of grounding device:		Bearing DE Size:	6314
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6210

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

\_



# **Mechanical Inspection (Continued)**

Seals DE condition :	Other	Brg. Seats DE:	Good	
Seals DE type:	Slinger	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	None	Shaft damage:	ОК	
Seals ODE type:	N/A			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	5.9060	Foot flatness:	Pass	
Endbell DE insulated?:	Endbell DE insulated?: —		stomer or EASA spec(<10%	
Endbell ODE size:	3.5440	variation)?		
Endbell ODE insulated?:	_	_		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

**Component Failure** 

**Cause of Failure** 

Comments

Windings are blown and one of the leads was open. Recommend new bearings and a rewind

Service Tech name: Ch

Chris Wiley

Service Tech signature:

Chard Clind

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301