

Job Information

Job #: 96710 Date: April 6, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: NLR Wastewater Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: US Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled
Serial#: Model#: 17706798-100

Service Factor: 1.15 Frame: 254ZHPZ

Horsepower/kW: 15 Rated RPM: 1775

Rated Amps: 89-35 Rated Voltage: 230-460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:









Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Grease

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 5212

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6207

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: Full Grease Cond. DE: Charred

Grease Amt ODE: Full Grease Cond. ODE: Charred

Seals DE type: Isolators

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: Slinger

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:



Fax 901-873-5301



Brg. Image:




Water jacket: N/A Fan: Ok Frame cond.: Good



Endbell type: Single piece

Missing parts? Endbell Image:

Horizontal/Foot mount



Motor Mount Position:





☐ HH cover





✓ None

Other missing parts





Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

Length of leads: 7in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Worn 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type: Insulation

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Dull black Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 5212

Shaft runout(TIR-Inbound): .004 Bearing ODE Size: 6207

Retainer condition: Good

ax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Isolators If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

2.8360 BAD

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 4.3314 Foot flatness: Pass

Endbell DE insulated?: —

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:



Conclusion

Component Failure

Cause of Failure

Comments

ODE bearing fit for the end bell is over sized, the winding strings are melted, the winding insulation is brittle, and the DE seal is bad. Recommend new bearings, new seal, rewind, and machine work.

Mehlly

Service Tech name: Chris Wiley

Service Tech signature:

Fax 901-873-5301