

Job Information

Job #:	96750				Date:	April 13, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

Customer Information

Name:	AFT	Reason:		
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

Name Plate Information

Manufacturer:	Bartec Varnost	Enclosure :	Totally Enclosed Fan Cooled
Serial#:	355	Model#:	
Service Factor:		Frame:	180M
Horsepower/kW:	26KW	Rated RPM:	3525
Rated Amps:	71	Rated Voltage:	460
Phase:	3	Cycles:	60
Special design:	No		

Enclosure Type image



Nameplate

DE

ODE

F1







Тор

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No	Contaminant Image:	
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	FAG
Insulated:	No	Bearing DE Size:	6310
Bearings ODE:	Worn	Bearings ODE make:	FAG
Bearing Type:	Ball	Bearing ODE Size:	6310
Bearings Retainer:	Yes	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

Bearing Type Image



Bearing Make Image



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

Bearing Retainer Image



Thermal Protection





Mechanical Inspection (Continued)

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Mobile Polyrex EM	Thermal Protection device ODE:	_
Lubrication brand outbound:	Mobile Polyrex EM		
Grease Amt DE:	Full	Grease Cond. DE:	New
Grease Amt ODE:	Full	Grease Cond. ODE:	New
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	



VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Brg. Image:




Water jacket: Ok



Fan: Ok







Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

ingle piece

Missing parts?

J-Box cover

HH cover

ver 🗌 Glands

O-rings



J-Box

Endbell Image:





Other missing parts

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Air Gap Meaurements (N/A on Single Piec	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	


AC Electrical Inspection

Number of leads:	6	Terminal Markings:	1-6	
Length of leads:	12	REF: NEMA Stds. Markings Identifie		2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Good	4-Yellow	8-Red	
Lug type:		Connections As Reco	eived: 460	
Lug Condition:	Good	Τε	erminal	Lugs
Lug size:				
Lug Attachment:	—			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



AC Electrical Inspection (Continued)

Winding colo	r: Like ne	w Winding	g image Windir	ng Thermal Protectio	on: Yes
Winding condition	: Solid				
Winding Therma Protection DE					
Winding Therma Protection ODE					
Stator test results	s: Salvago	eable			
Megs incoming:	Good	Surge incoming:	Good	Hi-pot incoming:	Good
Winding Resistance	e Incoming				
Р	hases A to B	Phases B to C	Phases C to A	A Resistive	e imbalance
Incoming	0.00	0.00	0.00	0.00	
Leads/ju If other, leads/ju	-	Dk	Lead jumpe	r Image. :	
Mechanical Inspection Inspect bolt holes and fasteners. Validate correct fasteners.					
Shaft (Condition:	Good	Bearings Retair	ner: Yes	

Bearing DE Size:

Bearing ODE Size:

6310

6310

Type of grounding device:

Shaft runout(TIR-Inbound):

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Mechanical Inspection (Continued)

Seals DE condition :	Worn	Brg. Seats DE:	Good
Seals DE type:	N/A	If DE undersized, amt.:	1.9686
Seals DE size:		Brg. Seats ODE:	Good
Seals DE (inbound) condition :		If ODE undersized, amt.:	1.9689
Seals ODE condition :	Worn	Shaft damage:	ОК
Seals ODE type:	N/A		
Seals ODE size:		Bushings/sleeves DE:	Ok
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok
Endbell fits/damage:	Good	Foot/Flange condition:	Ok
Endbell DE size:	4.333	Foot flatness:	Pass
Endbell DE insulated?:	No		stomer or EASA spec(<10%
Endbell ODE size:	4.3315	variation)?	
Endbell ODE insulated?:	No		

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



Conclusion

Component Failure

Cause of Failure

Comments

Wash and bake new bearings and Ageis ring

Service Tech name:

Robert Wiley

Service Tech signature:

Vile f I

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301