

Job Information

Job #: 96822 Date: May 8, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Sage V Foods Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Baldor Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: C0906010023 Model#:

Service Factor: 1.15 Frame: 326TDZ

Horsepower/kW: 50 Rated RPM: 1775

Rated Amps: 114/57 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top









Fax 901-873-5301



Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size: 6312-2RS

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6311-2RS

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Labyrinth

Seals DE size:

Seals DE (inbound) condition: Good

Seals ODE type: Labyrinth

Seals ODE size:

Seals ODE (inbound) condition

Good

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

Length of leads: 12 in REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Lug type: NA Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —

Fax 901-873-5301



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6312

Shaft runout(TIR-Inbound): Bearing ODE Size: 6311

Retainer condition: Good

ax 901-873-5301



Seals DE condition: Other Brg. Seats DE: Good

Seals DE type: Labyrinth If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Other Shaft damage: OK

Seals ODE type: Isolators

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Foot/Flange condition: Bad Ok

Endbell DE size: 5.1124 Foot flatness: **Pass**

Endbell DE insulated?:

4.7259

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE insulated?:

Endbell ODE size:



Conclusion

Component Failure

Cause of Failure

Comments

Both bearings show normal signs of wear, aegis ring is worn, both end bells are over sized. Recommend reconditioning, new bearings, new aegis ring, and machine work on both end bells.

Chen Eldus

Service Tech name: Chris Wiley

Service Tech signature: