

Job Information

96895 Job #: Date: May 29, 2020

Priority: Authorized OT: No Authorized by:

Customer Information

Name: Curwood Reason:

Contact: Motor#: PO#:

Application: Special notes:

Name Plate Information

Manufacturer: **Brook Compton** Enclosure: Totally Enclosed **Enclosure Type image**

Fan Cooled

Serial#: D517931 Model#:

Service Factor: **D132MD** Frame:

Horsepower/kW: 10 Rated RPM: 1740

Rated Amps: 25.0/12.5 Rated Voltage: 230/460

Cycles: Phase: 3 60

Special design:

No

Nameplate DE ODE F1 F2 Top











Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:

Contaminant(s): None

Shaft rotation: — Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: NU 308 ecp

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6308 2RS

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Unknown Thermal Protection device ODE:

Lubrication brand outbound: Unknown

> Grease Amt DE: Full Grease Cond. DE: Gritty

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: Seals Image: Isolators

Seals DE size: 40*52*7

Seals DE (inbound) condition: Worn

> Seals Image 2: Seals ODE type: Isolators

Seals ODE size: 25*35*7

Seals ODE (inbound) condition Worn

Shaft damage cause: Shaft Image: None





Brg. Image:



Water jacket: N/A Fan: Ok Frame cond.:





Good

Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 9 Terminal Markings:

Length of leads: 6" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars:

Rotor

Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass


Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6308 2RS

Shaft runout(TIR-Inbound): Bearing ODE Size: 6305 2RS

Retainer condition: —



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Isolators If DE undersized, amt.:

Seals DE size: 40*52*7 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Isolators

Seals ODE size: 25*35*7

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: Punched Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

2.4414



Conclusion

Component Failure

Seals & D.E. Housing fit bad.

Cause of Failure

Comments

Service Tech name: Terrence Holland

Service Tech signature: