

Job Information

Job #: 96979 Date: June 22, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Dewafelbakker Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Breddo Likwifer Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: P27040 Model#: T-MTR3035-1

Service Factor: 1.0 Frame: 324TCV

Horsepower/kW: 40 Rated RPM: 1770

Rated Amps: 94.8/47.4 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device

present?:

Type of grounding device: None

Shaft runout(TIR-Inbound):

Bearings DE: Worn Bearings DE make: FAG

Insulated: No Bearing DE Size:

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size:

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection



Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: Full Grease Cond. DE: Hard

Grease Amt ODE: Full Grease Cond. ODE: Gritty

Seals DE type: Seals Image: Slinger

Seals DE size:

Seals ODE type:

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

Shaft damage cause: None

N/A

Shaft Image:



Fax 901-873-5301



Brg. Image:



Bushings/sleeves image:



Water jacket:

N/A

Fan:

Ok

Frame cond.:

Good



Motor Mount Position:

Horizontal/Foot mount

Endbell type:

Single piece

Missing parts?

Endbell Image:

✓ J-Box cover

O-rings

☐ J-Box

☐ HH cover

Glands

☐ None

Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 12 Terminal Markings:

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Lug type: Connections As Received:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars:

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image:





AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: — Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6312 2Z

Shaft runout(TIR-Inbound): Bearing ODE Size: 6212 2Z

Retainer condition: Good



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: If DE undersized, amt.: Slinger

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: N/A

Bushings/sleeves DE: Ok Seals ODE size:

Bushings/sleeves ODE: Ok Seals ODE (inbound) condition:

> Endbell fits/damage: Foot/Flange condition: Good Ok

Endbell DE size: 5.1185 Foot flatness: **Pass**

Endbell DE insulated?:

4.3312

Does Air Gap Meet Customer or EASA spec(<10% variation)?

Endbell ODE insulated?:

Endbell ODE size:

Terrence Holland



Conclusion

Component Fai	ilure
---------------	-------

Bearings

Cause of Failure

Bearings worn and grease contaminated.

Comments

All machine fits check good.

Service Tech name: Terrence Holland

Service Tech signature: