

## **Job Information**

Job #:	97021				Date:	July 2, 2020
Priority:	_	Authorized OT:	No	Authorized by:		

### **Customer Information**

Name:	Kroger		Reason:	
Contact:		Motor#:		PO#:
Application:	_	Special notes:		

### **Name Plate Information**

Manufacturer:	Lincoln	Enclosure :	Open Drop Proof (ODP)
Serial#:	U3951109887	Model#:	
Service Factor:	1.15	Frame:	254T
Horsepower/kW:	5	Rated RPM:	880
Rated Amps:	18.7/9.35	Rated Voltage:	230/460
Phase:	3	Cycles:	60

#### Enclosure Type image



Nameplate

Special design:

DE

No

ODE

F1

F2

Тор







WEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



## **Mechanical Inspection**

#### Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?:	Yes	Contaminant(s):	None
Shaft rotation:	Bi-directional	Contaminant(s) Amt:	None
Shaft grounding device present?:	No		
Type of grounding device:			

Shaft runout(TIR-Inbound):

Bearings DE:	Worn	Bearings DE make:	Other
Insulated:	No	Bearing DE Size:	6309
Bearings ODE:	Worn	Bearings ODE make:	Other
Bearing Type:	Ball	Bearing ODE Size:	6208
Bearings Retainer:	No	Thermal Protection:	Yes
Retainer condition:	_	Thermal Protection Type:	_

#### Bearing Type Image



Bearing Make Image

Bearing Retainer Image

**Thermal Protection** 



WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **Mechanical Inspection (Continued)**

Lubrication Type:	Grease	Thermal Protection device DE:	_
Lubrication brand inbound:	Unknown	Thermal Protection device ODE:	_
Lubrication brand outbound:	Unknown		
Grease Amt DE:	Full	Grease Cond. DE:	Watery
Grease Amt ODE:	Full	Grease Cond. ODE:	Hard
Seals DE type:	N/A		
Seals DE size:			
Seals DE (inbound) condition :			
Seals ODE type:	N/A		
Seals ODE size:			
Seals ODE (inbound) condition :			
Shaft damage cause:	None	Shaft Image:	

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### **Mechanical Inspection (Continued)**

Brg. Image:



Water jacket:	N/A
---------------	-----

N/A

Fan:

N/A

Frame cond.: Good



 Motor Mount Position:
 Horizontal/Foot mount
 Endbell type:
 Single piece

 Missing parts?
 Endbell Image:
 Endbell Image:
 Image:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301

Other missing parts





## **Mechanical Inspection (Continued)**

Air Gap Meaurements (N/A on Single Pie	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
DE @ 0	ODE @ 0	_
DE @ 90	ODE @ 90	
DE @ 180	ODE @ 180	
DE @ 270	ODE @ 270	

## **AC Electrical Inspection**

Number of leads:	9	Terminal Markings:		
Length of leads:	5"	REF: NEMA Sto Markings Identif	ds. MG 1-2009, Rev. 1- fied By Color:	2010, 2.41-Terminal
Size of leads:		1-Blue 2-White 3-Orange	5-Black 6-No color assigned 7-No color assigned	P1-No color assigned P2-Brown
Lead condition:	Worn	4-Yellow	8-Red	
Lug type:		Connections As Re	eceived:	
Lug Condition:	-		Terminal	Lugs
Lug size:				
Lug Attachment:	_			

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



# **AC Electrical Inspection (Continued)**

Rotor Type:	Cast Aluminum		Rotor
Rotor Condition:	Ok Num roto		ALL IT I
Rotor Test Results			
Visual: Pass	Growler: Pass	Single phase:	Pass
Stator type: Stator condition:	Factory Ok I	If other, stator type: f other, stator condition:	
Failure location:	In slot	If other, stator failure:	
Stator Image:		Failure Image:	

VEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



### **AC Electrical Inspection (Continued)**

Winding color:	Like new	Winding	g image W	/inding Thermal	Protection:	Yes
Winding condition :	Solid					
Winding Thermal Protection DE:	_					
Winding Thermal Protection ODE:	_					
Stator test results:	Rewind					
Megs incoming: G	àood	Surge incoming:	Good	Hi-pot inc	oming:	Good
Winding Resistance I	ncoming					
Pha	ses A to B	Phases B to C	Phases (	C to A	Resistive ir	nbalance
Incoming						
Leads/jump	oers: Ok					
If other, leads/jump	pers:					

## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition:	Good	Bearings Retainer:	Yes
Type of grounding device:		Bearing DE Size:	6309
Shaft runout(TIR-Inbound):		Bearing ODE Size:	6208

Retainer condition:

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301 CENTRAL ARKANSAS 6812 Lindsey Rd. Little Rock, AR 72206 Phone 501-375-9178 Fax 501-375-4254

\_\_\_\_



# **Mechanical Inspection (Continued)**

Seals DE condition :	None	Brg. Seats DE:	Good	
Seals DE type:	N/A	If DE undersized, amt.:		
Seals DE size:		Brg. Seats ODE:	Good	
Seals DE (inbound) condition :		If ODE undersized, amt.:		
Seals ODE condition :	Worn	Shaft damage:	ОК	
Seals ODE type:	Slinger			
Seals ODE size:		Bushings/sleeves DE:	Ok	
Seals ODE (inbound) condition :		Bushings/sleeves ODE:	Ok	
Endbell fits/damage:	Good	Foot/Flange condition:	Ok	
Endbell DE size:	3.9374	Foot flatness:	Pass	
Endbell DE insulated?:	_	Does Air Gap Meet Cu	Does Air Gap Meet Customer or EASA spec(<10% variation)?	
Endbell ODE size:	3.1495	variation)?		
Endbell ODE insulated?:	No			

VEST TENNESSE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300 Fax 901-873-5301



#### Conclusion

#### **Component Failure**

#### **Cause of Failure**

Bearings worn and water was inside the stator and end bell housing fits. One lead had worn insulation and require sleeving.

#### Comments

Bearings worn and water was inside the stator and end bell housing fits. One lead had worn insulation and require sleeving. Motor also had a live wasp nest inside attached to the rotor.

Service Tech name: Terrence Holland

Service Tech signature:

Hilla J

WEST TENNESSEE 7030 Ryburn Drive Millington, TN 38053 Phone 901-873-5300

Fax 901-873-5301