

Job Information

Job #: 97031 Date: July 14, 2020

Priority: — Authorized OT: No Authorized by:

Customer Information

Name: Welspun Reason:

Contact: Motor#: PO#:

Application: – Special notes:

Name Plate Information

Manufacturer: Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: 2941 Model#: YEB160L-8

Service Factor: Frame: 160L

Horsepower/kW: 7.5 Rated RPM: 870

Rated Amps: 18 Rated Voltage: 460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:







Mechanical Inspection

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE:

Worn

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Insulated: No Bearing DE Size: 6309 2RS

Bearings ODE: Worn Bearings ODE make: Other

Bearing Type: Ball Bearing ODE Size: 6309 2RS

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Bearings DE make:

Other

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE:

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE:

Lubrication brand outbound: Mobile Polyrex EM

> Grease Amt DE: 0 Grease Cond. DE: Other

Grease Amt ODE: Grease Cond. ODE: Other

Seals DE type: Seals Image: Slinger

Seals DE size:

Seals ODE type:

Seals ODE size:

Seals ODE (inbound) condition

Seals DE (inbound) condition:

N/A

Shaft damage cause: Shaft Image: None





Brg. Image:



Bushings/sleeves image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

AC Electrical Inspection

Number of leads: 3 Terminal Markings:

Length of leads: 4" REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received: Lug type:

Lug size:

Lug Condition:

Lug Attachment: Acceptable

Good

Terminal



Lugs





AC Electrical Inspection (Continued)

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



Rotor Test Results

Rotor Condition:

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image: Failure Image:







AC Electrical Inspection (Continued)

Winding color: Like new Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal ____ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

Winding Resistance Incoming

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

Mechanical Inspection

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6309

Shaft runout(TIR-Inbound): .002 Bearing ODE Size: 6309

Retainer condition: —

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Slinger If DE undersized, amt.:

Seals DE size: 45*60*7 Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: Worn Shaft damage: OK

Seals ODE type: Slinger

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 3.9370 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

3.9373



Conclusion

(C	ი	m	าท	O	n	ei	nt	F	ai	lı	ш	re
	_	v		ı	v		v			uı	ш	м	

Cause of Failure

Seal, and broken connection block for the leads. Also

Comments

D.E. Seal failed allowing oil to saturate the winding coils. The connection block for the leads is broken and needs to be replaced. The connection box bottom half is bent and worn.

Terrence Holland

Service Tech name: Terrence Holland

Service Tech signature: