

### **Job Information**

97061 Job #: Date: July 14, 2020

Priority: Authorized OT: No Authorized by:

## **Customer Information**

Name: Central Arkansas water Reason:

Contact: Motor#: PO#:

Application: Special notes:

## **Name Plate Information**

Manufacturer: Us Enclosure: Open Drop Proof **Enclosure Type image** 

(ODP)

C60175569085110 Serial#: Model#:

60

Service Factor: 5006tp 1.15 Frame:

Horsepower/kW: 200 Rated RPM: 1185

Rated Amps: 224 Rated Voltage: 460

Phase: 3 Cycles: 60

Special design:

No

Nameplate DE ODE F1 F2 Top













Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): None

Shaft rotation: CCW Contaminant(s) Amt: None

Shaft grounding device

present?:

No

Type of grounding device:

Shaft runout(TIR-Inbound): Good

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 7226bcbm

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 62192zc3gjn

Bearings Retainer: Yes Thermal Protection: Yes

Retainer condition: Good Thermal Protection Type: RTD

Bearing Type Image



Bearing Make Image



Bearing Retainer Image



Thermal Protection





Lubrication Type: Oil Thermal Protection device DE: Thermistors

Lubrication brand inbound: Unknown Thermal Protection device ODE: N/A

Lubrication brand outbound: Unknown

Grease Amt DE: N/A Grease Cond. DE: New

Grease Amt ODE: N/A Grease Cond. ODE: New

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Vertical Flange mount Endbell type: Single piece

Missing parts? Endbell Image:

✓ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☐ None

Other missing parts







Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0

DE @ 90 **ODE @ 90** 

DE @ 180 **ODE @ 180** 

DE @ 270 **ODE @ 270** 

## **AC Electrical Inspection**

Number of leads: 6 Terminal Markings:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal Length of leads: 8"

Markings Identified By Color:

P1-No color assigned 5-Black 1-Blue Size of leads: 4 awg P2-Brown

2-White 6-No color assigned

3-Orange 7-No color assigned

4-Yellow 8-Red Lead condition: Good

Connections As Received: Copper Lug type:

Lug Condition: Good Terminal Lugs

Lug size: Same Lug Attachment:



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 84

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: Other If other, stator failure:

Stator Image:





## **AC Electrical Inspection (Continued)**

Winding color: Still has color Winding image Winding Thermal Protection: Yes

Winding condition: Solid

Winding Thermal Good Protection DE:

Winding Thermal Protection ODE:

Stator test results: Salvageable

Megs incoming: Surge incoming: Hi-pot incoming: Good Good Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

**Shaft Condition:** Bearings Retainer: Yes Good

Type of grounding device: Bearing DE Size: Same

Shaft runout(TIR-Inbound): Bearing ODE Size: Good Same

Retainer condition: Good

CENTRAL ARKANSAS



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 9.0562 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

6.6938



### Conclusion

### **Component Failure**

Bearings, one thermistor, windings meg low

#### **Cause of Failure**

Normal wear

#### **Comments**

Has oil film on bottoms of the endbells but none in the stator or on the rotor.

Service Tech name: Trevor Hall

Service Tech signature:

7-74/