

### **Job Information**

Job #: 97078 Date: July 15, 2020

Priority: — Authorized OT: No Authorized by:

# **Customer Information**

Name: Arauco Reason:

Contact: Motor#: PO#:

Application: – Special notes:

### **Name Plate Information**

Manufacturer: TECO Enclosure: Totally Enclosed Enclosure Type image

Fan Cooled

Serial#: RH7183716-003 Model#:

Service Factor: 1.15 Frame: 365T

Horsepower/kW: 75 Rated RPM: 1775

Rated Amps: 170.2/85.1 Rated Voltage: 230/460

Phase: 3 Cycles: 60

Special design: No

Nameplate DE ODE F1 F2 Top







Fax 901-873-5301



## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: No Contaminant(s): Grease

Shaft rotation: Bi-directional Contaminant(s) Amt: Other

Shaft grounding device

present?: Contaminant Image:

Type of grounding device:

Shaft runout(TIR-Inbound):

Bearings DE: Fell Apart Bearings DE make: FAG

Insulated: No Bearing DE Size: 6313

Bearings ODE: Worn Bearings ODE make: FAG

Bearing Type: Ball Bearing ODE Size: 6213

Bearings Retainer: Yes Thermal Protection: No

Retainer condition: Good Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: -

Lubrication brand inbound: Unknown Thermal Protection device ODE: —

Lubrication brand outbound: Unknown

Grease Amt DE: 1/4 Grease Cond. DE: Watery

Grease Amt ODE: Full Grease Cond. ODE: Other

Seals DE type: N/A

Seals DE size:

Seals DE (inbound) condition:

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Water jacket: Ok Fan: Ok Frame cond.: Good Motor Mount Position: Horizontal/Foot mount Endbell type: Single piece Missing parts? O-rings ☐ J-Box cover ☐ J-Box ☐ HH cover ☐ Glands ☐ None

Other missing parts



Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

**AC Electrical Inspection** 

Number of leads: 12 Terminal Markings:

Length of leads:

REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 10 in 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown 3-Orange 7-No color assigned

Lead condition: Good 4-Yellow 8-Red

Connections As Received:

Lug Condition: Good Terminal Lugs

Lug size:

Lug type:

Lug Attachment:



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 40

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Ok If other, stator condition:

Failure location: In slot If other, stator failure:

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Still has color Winding image Winding Thermal Protection: No

Winding condition: Solid

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal Protection ODE:

Stator test results: Rewind

Megs incoming: Good Surge incoming: Good Hi-pot incoming: Good

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming 0.00 0.00 0.00

Leads/jumpers: Ok Lead jumper Image. :

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: Yes

Type of grounding device: Bearing DE Size: 6313

Shaft runout(TIR-Inbound): Bearing ODE Size: 6213

Retainer condition: Good

Fax 901-873-5301



Seals DE condition: None Brg. Seats DE: Good

Seals DE type: N/A If DE undersized, amt.:

Seals DE size: Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Bad Foot/Flange condition: Ok

Endbell DE size: 5.5136 Foot flatness: Pass

Endbell DE insulated?: —

4.7258

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: -

Endbell ODE size:



### Conclusion

Component Failu	lure
-----------------	------

DE bearing, windings

#### **Cause of Failure**

DE bearing went out

#### **Comments**

Recommend new bearings, rewind, machine work on DE endbell and DE shaft bearing fit

Char heles

Service Tech name: Chris Wiley

Service Tech signature: