

#### **Job Information**

Job #: 97087 Date: July 20, 2020

Priority: — Authorized OT: No Authorized by:

### **Customer Information**

Name: ENTERGY white bluff Reason:

Contact: Motor#: PO#:

Application: – Special notes:

### **Name Plate Information**

Serial#:

Manufacturer: Limitorque Enclosure: Open Drop Proof Enclosure Type image

(ODP)

B71021704-ug Model#:

Service Factor: Frame: L56

Horsepower/kW: 0.70 Rated RPM: 1700

Rated Amps: 24/12 Rated Voltage: 230/460

Phase: 3 Cycles: 60

No

Nameplate DE ODE F1 F2 Top



Special design:













## **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Does the shaft turn freely?: Yes Contaminant(s): Other

Shaft rotation: Bi-directional Contaminant(s) Amt: None

Shaft grounding device No Contaminant Image:

present?:

Shaft runout(TIR-Inbound): 0.001

Type of grounding device:

Bearings DE: Worn Bearings DE make: SKF

Insulated: No Bearing DE Size: 6203 2zc3 gjn

Bearings ODE: Worn Bearings ODE make: SKF

Bearing Type: Ball Bearing ODE Size: 6203 2zc3 gjn

Bearings Retainer: No Thermal Protection: No

Retainer condition: — Thermal Protection Type: —

Bearing Type Image



Bearing Make Image



Bearing Retainer Image

Thermal Protection



Lubrication Type: Grease Thermal Protection device DE: —

Lubrication brand inbound: Mobile Polyrex EM Thermal Protection device ODE: —

Lubrication brand outbound: Mobile Polyrex EM

Grease Amt DE: Full Grease Cond. DE: New

Grease Amt ODE: Full Grease Cond. ODE: New

Seals DE type: Isolators Seals Image:

Seals DE size: .75x1.25x0.25

Seals DE (inbound) condition: Worn

Seals ODE type: N/A

Seals ODE size:

Seals ODE (inbound) condition

:

Shaft damage cause: None Shaft Image:





Brg. Image:



Water jacket: N/A Fan: N/A Frame cond.: Good



Motor Mount Position: Vertical Flange mount Endbell type: Single piece

Missing parts? Endbell Image:

☐ J-Box cover ☐ O-rings ☐ J-Box

☐ HH cover ☐ Glands ☑ None

Other missing parts







#### Air Gap Meaurements (N/A on Single Piece Endbell)

Does Air Gap Meet Customer or EASA spec(<10% variation)?

DE @ 0 ODE @ 0 -

DE @ 90 ODE @ 90

DE @ 180 ODE @ 180

DE @ 270 ODE @ 270

## **AC Electrical Inspection**

Number of leads: — Terminal Markings:

Length of leads: REF: NEMA Stds. MG 1-2009, Rev. 1-2010, 2.41-Terminal

Markings Identified By Color:

Size of leads: 1-Blue 5-Black P1-No color assigned

2-White 6-No color assigned P2-Brown

3-Orange 7-No color assigned

Lead condition: Bad 4-Yellow 8-Red

Connections As Received: Lug type:

Lug Condition: — Terminal Lugs

Lug size:

Lug Attachment: —



# **AC Electrical Inspection (Continued)**

Rotor Type: Cast Aluminum

Ok

Num rotor bars: 44

Num broken bars: 0

Rotor



#### **Rotor Test Results**

**Rotor Condition:** 

Visual: Pass Growler: Pass Single phase: Pass

Stator type: Factory If other, stator type:

Stator condition: Roast-out If other, stator condition:

Failure location: Other If other, stator failure: Overload

Stator Image: Failure Image:







## **AC Electrical Inspection (Continued)**

Winding color: Painted Winding image Winding Thermal Protection: No

Winding condition: Charred

Winding Thermal \_\_\_\_ Protection DE:

Winding Thermal
Protection ODE:

Stator test results: Rewind

Megs incoming: Bad Surge incoming: Bad Hi-pot incoming: Bad

**Winding Resistance Incoming** 

Phases A to B Phases B to C Phases C to A Resistive imbalance

Incoming

Leads/jumpers: Ok

If other, leads/jumpers:

# **Mechanical Inspection**

Inspect bolt holes and fasteners. Validate correct fasteners.

Shaft Condition: Good Bearings Retainer: No

Type of grounding device: Bearing DE Size: 6203 2zc3

Shaft runout(TIR-Inbound): 0.001 Bearing ODE Size: 6203 2zc3

Retainer condition: —

Fax 901-873-5301



Seals DE condition: Worn Brg. Seats DE: Good

Seals DE type: Isolators If DE undersized, amt.:

Seals DE size: Same Brg. Seats ODE: Good

Seals DE (inbound) condition: If ODE undersized, amt.:

Seals ODE condition: None Shaft damage: OK

Seals ODE type: N/A

Seals ODE size:

Bushings/sleeves DE: Ok

Seals ODE (inbound) condition : Bushings/sleeves ODE: Ok

Endbell fits/damage: Good Foot/Flange condition: Ok

Endbell DE size: 1.5753 Foot flatness: Pass

Endbell DE insulated?: No

Does Air Gap Meet Customer or EASA spec(<10%

variation)?

Endbell ODE insulated?: No

Endbell ODE size:

1.5752



#### Conclusion

Component Failure	Com	ponent	Failure
-------------------	-----	--------	---------

Windings, bearings, seal

**Cause of Failure** 

Overload

**Comments** 

Service Tech name: Trevor Hall

Service Tech signature:

/~pll